



Overview: Part of spill impact on 8" Obigbo North New Elenwo pipeline at Akpajo. Picture taken during Joint Investigation of 19th August, 2011.



Close-up: Spill due to corrosion on 8" Obigbo North New Elenwo pipeline at Akpajo. Picture taken during Joint Investigation of 19th August, 2011.