JOINT INVESTIGATION REP	ORT FOR INCIDENT N	o:0104	706505
(Note: As practicable as possible the JIT r	eport is to be signed in th		
A. GENERAL INFORMATION:	3	- y · · · · · · · · · · · · · · · · · ·	cipating parties)
	_		
1. Spill incident Number:	5 2. Type	of incident*_OIL	SPILL
3. Name of Location 20" Kol	OCREEK - RU	MUEKPE P	IPELINE
Name of nearest community OGBOG	5. State: R	VFRS 6.LGA	AHAANA - WEST
7. Type of Production facility/Installation	PIDEL INE	Agget grown and Direction	MEADA WEST
B. INCIDENT INFORMATION:	o.	Asset Owner/District	NESP/KOLOCREEK
b. Date/Period of investigation 47	H, 9TH TO	=	TEMBER, 2011
 c. Description of spill point environs Firmed soil 			
Under water	□ Loose soil	☐ Previously exca	
☐ Well Platform (on Water)	☐ Swampy	☐ Exposed pipe s	urface
d. Description of leak point (tick as a	nnlicable).	□ Rig	
☐ Drilled hole	□ Hack saw cut	☐ Explosive tear,	
☐ Complete Rupture	☐ Inward dent,	☐ Well head tamp	onia o
☐ Failed Weld-on illegal hot tap v		☐ Missing Pipelin	•
☐ Crude oil theft (illegal bunkerin		☐ Third party tam	-
☐ Third party tampering with valv		☐ Third party tam	=
□ External Corrosion	•	☐ Internal Corros	
☐ Saver-pit over flow,	☐ Surge vessel overflow		1011
☐ Flare System/Bund wall Failure		com unit failure	•
□ Cold vent	☐ Relief valve failure		FAILED CLAMP
e. Incident due to:		~ .	
☐ Third party interference	Operational	☐ Others (speci	TY NOT APPLICABLE
Measuring unit M	NA MID-BELT)		
Northing:		Easting:	
104913.44	•	454951.	03

Page 1 of 9

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0104 706505

C.	RISK ASSESSI	MENT						
	10. Ty	pe of enviro	onment:	>				
	Land	□Sw	amp 🗆 '	Water [☐ Seasonal swamp			
	і. Тур	e of enviror	nment to which	oil has spread:				
	Land	□ Sw	amp 🗆 🗅 🛚	Water E	☐ River (identify)	T APPLIC	ABLE	
	ii. We	ather conditi	ion					
	Raining 11. Distance from			tat				
	Drinking Built up Farmlan Fish Far Fishing Others (12. Containment	g water sour area ads m/Pond net specify). t measures p	NOT AP out in place;	PLI CABLE Dyke	[,m] [,m] [,m] ,m]			
	13. Any pictures	or video co	verage?		[Y] [N]			
	14. Was there and the ser give brief descr	ON BE iption: JIV	THE 411 Convinc Was Ter	h of Aug Ingly Lin Imed Inc	ust , 2011, the s uked to the l onclusive, open	PIPELINE NING UP	AND TH AND PRE	IE Ssur
					S. BY THIS TIME			
LE	AKING FROM TYPE/NUMBER	S OF PRO	10- 20" X	24" FAIL	ED CLAMP WITH WITHIN THE AREA O	BROKEN	SEAL.	
	15. Structures /	Properties						
S/N	Type of Strue	ctures	Description	Size	Number	Comments		

NONE WITHIN AREA OF IMPACT

JOINT INVESTIGATION REPORT FOR INCIDENT NO: U104 706505

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
M	ONF	WITHIN	AREA	1 NF	IMPAC	T
		X			UNITE	


17. Fish/Nets/Ponds

S/N	Fish/Nets/I	Ponds	Descript	ion	Quantity/	Size	Comments
M	ONE	WI	HIN	AREA	OF	IN	PACT

18. Others (Specify) i.e. Animal Traps

S/N Others	Description	¿uantity/Size	Comments
NONE	WITHIN	AREA OF !	MPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0104706505

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2) (MINNA MID-BELT)


S/N	Northing (M)	Easting (M)
305	104910.26	454987.99
306		454991.08
307	104907-16	454997.24
308	104904.23	454998.06
309	104901-01	454997.22
310	104901.04	454987-97
311	104 901.06	454978-73
312	104902-54	454967-09
313	104907.27	454957-17
314		454954.10
315	104910-37	454947.94
316	104913.45	454947.95
317	104913-42	45 4 957 19

G. INCIDENT INFORMATION:

20. Impac	cted A	rea D	etails
-----------	--------	-------	--------

Total calculated area of impact	0.04 Ha
Impact within SPDC R.O.W	0.04 Ha
Impact outside R.O.W	NIL
21. Volume of oil recovered before completion of JI	$\underline{V}(V_{rec})$:
Recovered oil V _{rec}	51.89 barrels
20. Computation of the residual volume on site	
 a. Computation of volume of pool of free phase oil (on least of the phase) i. Area (m²) occupied by pool of free phase 	e oil
ii. Average Depth (m) of pool of free phase	0.0011
iii. Emulsification factor: NIL	
iv. Volume of pool of free phase	oil. V _{rod} : Q.Q.1 barrels

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: b. Computation of volume of infiltrated oil in the soil (V_{inf}) . i. Area (m²) covered by the oil: ii. Area of the pool of free phase oil in touch with soil: NIL iii. Average Depth (m) below ground surface of infiltration of oil: 0.0 | 8 iv. Soil type: CLAY $P_{\rm e}$ (effective porosity of the soil). Volume of infiltrated oil, Vinf. iv. barrels 0.22 21. Computation of volume of oil on open water based on standard coloration. Total area of oil on open water: NIL ij. Table of average depth of oil on water based on coloration *



22. Calculation of evaporated volume:

Oil type: BONNY LIGHT

E-Factor: 25% ii.

iii. Volume of evaporated oil. V _{evap} : 20.64 barrels	iii. Volume of evaporated oil. V evap:
--	--

Evaporation Factors (E-Factor) for SPDC Crude oil						
Oil Type	Days on site	Bonny Light	Bonny Medium			
Period Since Oil Spill	< 1 day	10%	5%			
	1-7 days	25%	15%			
	> 7 days	40%	25%			

23. Gross Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_$ V_{pool} (bbls) + V_{recJ} (bbls) = 20.64 + NIL + 0.22 + 9.81 + 51.89 = 82.56 BARRELS


THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 706505

V _{Est} (bbls)= Q2-6 RARDELO	
- GZ & DITIVEED	
24. Net Total Estimated Spilled Volume V Est(bbls) = Vevap(bbls) + 0.6*Vwat (bbls)	
$V_{\text{pool}} \text{ (bbls)} + V_{\text{recJ}} \text{ (bbls)} = 20.64 + NL + 0.22 + 9.81 + 5 \\ 82.56 \text{ BARRELS}$	1.84 =
VEst(bbls)= 82.6 BARRELS	
Calculation of the respective estimated volume is to be done using the new spill estimation softw	are on site
Conversion of m3 to barrels is Total volume VT (m3) x 6.29 Emulsification factor for spill on water to consider is 60% of volume of oil.	
25. GENERAL STATUS OF THE SITE	
A. Joint investigation of the incident site found that there is no residual imp	act After the
initial response and therefore recommend that the site be closed out lue	
B. Investigation of the incident site showed that there is residual impact on further works	site requiring
26 Signatories	
This report was filled and signed on the	site by joint
Host Community	
• Department of Petroleum Resources [DPR]:	
• National Oil Spill Detection and Response Agency [NOSDRA]:	•
State Ministry of Environment [SME]:	
Nigeria Police Force [NPF]:	
Shell Petroleum Development Company [SPDC]:	
au	ick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: U104 706505

20. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 706505

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION (IMPACTED AREA BOUNDARY COORDINATES - MINNA MIDBELT)

S/N	Northing (M)	Easting (M)
318	10494.07	454954.86
319	104910-35	454957-18
320	104910.34	454960-26
321	104910.33	454963-35
322	104911.94	454963.01
323	104913.40	45 4963.35
324	104914.01	454964-64
325	104 913 - 39	454966.44
326	104912.01	454966.65
327	104910.32	454966.43
328	104910.28	454978.75
329	104910-27	454981.84
330	104913.36	454978.76
331	104916.42	454 981.85
332	104916.40	454988.02
333	104913-32	454991.09