



Overview: Part of the spill incident impact at 20" Kolocreek – Rumuekpe Pipeline route in Ogbogolo. Picture was taken during JIV of 4th and 9 – 11th September, 2011.



Close-up: Spill due to failed clamp point on 20" Kolocreek – Rumuekpe Pipeline at Ogbogolo. Insert shows broken seal of failed clamp. Pictures were taken during JIV of 4th and 9 – 11th September, 2011.