



26.02.2011 12:32

Overview: Extent of the spill incident impact on 28" Bomu-Bonny Pipeline at Bodo West .
Pictures taken during Joint Investigation of 26th February, 2011



27.02.2011 13:09

Close-up: Spill due to illegally welded points on 28" Bomu- Bonny Pipeline at Bodo West.. Picture taken during Joint Investigation of 27th February, 2011.