



Close-up: Failed clamp point on Awoba NorthWest Well 1 L/S flow line at Boro.  
Picture was taken during JIV of 19<sup>th</sup> May, 2011