



Close-up: Spill due to corrosion on 12" Adibawa-Okordia pipeline at Ikarama. Picture was taken during Joint Investigation of 16<sup>th</sup> November, 2011.