



Overview: Part of spill impact on 8" North bank Tie-in Manifold. Picture was taken during Joint Investigation of 2nd December, 2011.



Close-up: Failed barrel door on 8" North bank Tie-in Manifold. Picture was taken during Joint Investigation of 2nd December, 2011.