JOINT INVESTIGATION REPORT FOR INCIDENT NO:_____

JOINT INVESTIGATION REPO	ORT FOR INCIDENT NO	o: 0116 723956
(Note: As practicable as possible the JIT re	port is to be signed in the	,
A. GENERAL INFORMATION:	•	your of an one participating parties)
1. Spill incident Number: 72395	4 2.Type	of incident* SPILL
1. Spill incident Number: 72395 3. Name of Location 4." IMO Rive	RIWELL 30 S	FLOWLINE
4. Name of nearest community 19181	UKWU 5. State: A	BIA 6. LGA UKWA -WEST
7. Type of Production facility/Installation	THE FLOWLINE 8. A	BIK 6. LGA UKWA - WEST Asset owner/District NESP / LAND
3. INCIDENT INFORMATION:		
b. Date/Period of investigation: 6 7	TOBER 2011 HOCTOBER 2	<u> </u>
c. Description of spill point environm		<u></u>
☐ Firmed soil	Loose soil	☐ Previously excavated area
☐ Under water	□ Swampy	Exposed pipe surface
□ Well Platform (on Water)		□ Rig
d. Description of leak point (tick as ap	oplicable);	— 1····g
☐ Drilled hole	₩ Hack saw cut	☐ Explosive tear,
☐ Complete Rupture	☐ Inward dent,	☐ Well head tampering
☐ Failed Weld-on illegal hot tap va	alve,	☐ Missing Pipeline/Flowline)
□ Crude oil theft (illegal bunkering	g) point,	☐ Third party tampering with Clamp
☐ Third party tampering with valve	e setting,	☐ Third party tampering with flange,
□ External Corrosion	_	☐ Internal Corrosion
☐ Saver-pit over flow,	☐ Surge vessel overflow,	
☐ Flare System/Bund wall Failure		com unit failure
□ Cold vent	☐ Relief valve failure	☐ Others (specify)
- T13 3	•	— Carers (specify)
e. Incident due to: Third party interference	□ Operational	☐ Others (specify
f. Spill point coordinates		
Measuring unit	MINIM MID	BELI
Northing: (m)	Ē	Easting: (m)
108911-24		524099.58

Page 1 of 9

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0116 723 956

C.	RISK ASSESSMEN	łT				
	10. Type o	of environment:		•		
	Land	□ Swamp	□ Water	Seasonal swam	p	
	i. Type of	environment to	which oil has spr	ead:		
	☑ Land	☐ Swamp	□ Water	☐ River (identify)	· · · · · · · · · · · · · · · · · · ·	
	ii. Weathe	r condition				
	☐ Raining 11. Distance from th	Sunny ne nearest sensiti	ve habitat			
	☐ Governmen ☐ Drinking wa ☐ Built up are ☐ Farmlands ☐ Fish Farm/P ☐ Fishing net ☐ Others (spec	ater source ond cify).	esignated protecte LICARA ce;	['\uu	m] m] m]	
	□ Booms	☐ Trench	□ Dyke			
	□ Others: N	ATUKAL	DEFRE	1018		
	13. Any pictures or	video coverage?		EXX [[N]	
	14. Was there any d	isruption to the i	nvestigation?	[Y] [M	
If	es give brief descripti	on:				
	NOT	AP	PLICE	ABLE		

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

C.

S/N	Type of Structures	Description	Size	Number	Comments
		<u> </u>			
-	11/11/	171110	APS	ANTIN	10APT
-	NONEN	11 11 6.	· //FC	11 01 111	11 11 C
—					

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0116 7239

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
-	X19 -15		1 A 0 S	·	4.04.0	
	NONE	- WITHIN	l AKt	1 Dif-	IM PA	<u> </u>
		· · · · · · · · · · · · · · · · · · ·				 - · · · · · · · · · · · · · · · · · · ·

17. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description		Quantity/Size		Comments	
	NONE n	ITHIN	AR	EA	OF	IMPACT	

18. Others (Specify) i.e. Animal Traps

S/N	Others	D	escripti	ion	aantity	//Size	Comments
$\overline{}$	ONE	WIH	44	AKEA	06	IM	PACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)

A	SECTION	37	4" 1mo-Ri	ver 1 WEL	L 30S FLOWLINE	SHOWING
HAR	k saw cut	FROM	12701	0'eLock	POSITION	



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0116 723956

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

	MINNA- HUD BELT						
S/N	Northing (m)	Easting (n)					
14	108932.70	524121.19					
15	108920.42	524121-17					
16	108914.28	524118.07					
18	108895.85	52418.04					
19	108895 - 85	52414.96					
17	108895.87	524108.79					
20	108895 88	524102 63					
21	108883.60	524099.53					
24	108892.81	524099-55					
26	108895.90	524090.31					
27	108905 12	524090.33					
22	108883 - 59	524102.61					
30	108914.33	524090.35					

G. INCIDENT INFORMATION:

20	Impacted	Area	Details
711	THINKELER	AICA	T/Claus

•]	Total calculated area of impactO · [O Hea	<u> </u>	-
• I	Impact within SPDC R.O.W		-
. • I	Impact outside R.O.W		<u> </u>
21. Volume	of oil recovered before completion of JIV (Vrec)):	
	Recovered oil V _{rec} r.	NIL	barrels
	ation of the residual volume on site		
a. Computat	tion of volume of pool of free phase oil (on land or oi. Area (m²) occupied by pool of free phase oil	100	_
i	ii. Average Depth (m) of pool of free phase oil	0.002	-
ii	ii. Emulsification factor:	_	
	iv. Volume of pool of free phase oil. V poo	3.1	barrels

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED						
JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0116 723956						
b. Computation	of volume of infilt	rated oil in the soil (V _{inf})).			
	i. Area (m²) cove	ered by the oil:	980			
i	i. Area of the po-	ol of free phase oil in to	uch with soil: 180			
ii	i. Average Depth	n (m) below ground surf	ace of infiltration of oil: 0.505			
i		tal				
	-	orosity of the soil)	8%			
i	v. Volume o	f infiltrated oil. V _{inf}	2.5	barrels		
i. Total area o	of oil on open wate	- A	on standard coloration. FPLICABLE tion *			
	(mm)	coverage	Volume (m3)			
Barely Visible	0.00004	N N				
Silvery	0.00008					
Slight Color	0.00015	1 %				
Bright Color	0.0003	1.00	21			
Dull	0.001	1711	1 (4191			
Dark	0.002		·			
Blackoil	0.1	·				
Emulsion (30% Oil)	1					
	Percent Total	10	700% Total Volume MW	bbl		
iii. Volume of oil on open water. Vwat: barrels						
22. Calculation of	f evaporated vol	ume:				
i. Oil t	ype: BONN	Y MEDIUM				
	ctor: 15 c	<u> </u>				
ii	i. Volume of ev	aporated oil. V evap:	1 1	parrels		

Evaporation Factors (E-Factor) for SPDC Crude oil						
Oil Type	Days on site	Bonny Light	Bonny Medium			
Period Since Oil Spill	< 1 day	10%	5%			
	1-7 days	25%	15%			
	> 7 days	40%	25%			


23. Gross Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recl}(bbls) = 1 + NiL + 2.5 + 3.1 + NiL = 6.6 BARRELS$

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

VEST(bbls)= 6'-6 BARRELS			
24. Net Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + 0.6*V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls) = 1 + Nul + 2.5 + 3.1 + Nul = 6.6 BARLELS$			
VEst(bbls)= 6.6 BARRETS			
*Calculation of the respective estimated volume is to be done using the new spill estimation software on site *Conversion of m3 to barrels is Total volume VT (m3) x 6.29 *Emulsification factor for spill on water to consider is 60% of volume of oil.			
25. GENERAL STATUS OF THE SITE			
A. Joint investigation of the incident site found that there is no residual impact. After the initial response and therefore recommend that the site be closed out.			
B. Investigation of the incident site showed that there is residual impact on site requiring further works			
26 Signatories			
This report was filled and signed on the investigation representatives from			
• Host Community 🔽			
• Department of Petroleum Resources [DPR]: ☑			
 National Oil Spill Detection and Response Agency [NOSDRA]: 			
• State Ministry of Environment [SME]: □			
Nigeria Police Force [NPF]:□			
• Shell Petroleum Development Company [SPDC]: □			
Tick as applicable			

JOINT INVESTIGATION REPORT FOR INCIDENT NO. 0116 723956

20. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 72395(0116

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing (m)	Easting (m)
	1.00	- Cm
13	108926.61	524096.53
7.1		