JOINT INVESTIGATION REPORT FOR INCIDENT NO: 72743

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

	,	
A. GENERAL INFORMATION:		•
1. Spill incident Number: 7277	<u> </u>	of incident* SPILL
3. Name of Location 20" Bugn	uma -ALAKIRI	1 PIPELINE
4. Name of nearest community BAKA	5. State: Re	VERS 6. LGA DEGEMA
7. Type of Production facility/Installation	OUL PIPELINE 8. A	Asset owner/District NECP
B. INCIDENT INFORMATION:		
9. Details of incident	TOBER 2011	
a. Date of incident: 18		
b. Date/Period of investigation: 21	st to 2300 00	Tokek 2011
c. Description of spill point environs	ment	•
☐ Firmed soil	□ Loose soil	☐ Previously excavated area
Under water	♥ Swampy	☐ Exposed pipe surface
□ Well Platform (on Water)		□ Rig
d. Description of leak point (tick as		
☐ Drilled hole	☐ Hack saw cut	□ Explosive tear,
□ Complete Rupture	☐ Inward dent,	☐ Well head tampering
☐ Failed Weld-on illegal hot tap	-	☐ Missing Pipeline/Flowline)
☐ Crude oil theft (illegal bunkeri		☐ Third party tampering with Clamp
☐ Third party tampering with val	lve setting,	☐ Third party tampering with flange,
☐ External Corrosion		□ Internal Corrosion
☐ Saver-pit over flow,	☐ Surge vessel overflow	v, Outward dent
☐ Flare System/Bund wall Failur	e UValve Failure	□ com unit failure
□ Cold vent	☐ Relief valve failure	VOthers (specify) Punuted Hole
e. Incident due to:		
Third party interference	□ Operational	☐ Others (specify
6 Cuill maint accordinates		
f. Spill point coordinates Measuring unit	MINNA MID	Bat
Northing:		Easting:
8113812.	, N	499445 09mE
•		¥

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 727443

RIS	K ASSESSMEN	łŢ			
1	0. Type o	of environment:			
	□ Land	Swamp	Water	☐ Seasonal s	swamp
	i. Type of	environment to w	vhich oil has sprea	d:	
	□ Land	Swamp	Water	☐ River (ide	ntify)
	ii. Weather	r condition			
11.	☐ Raining Distance from the		e habitat		
12.	☐ Drinking wa	ater source Nond APP	LI CABLE	, , , , ,	人に,m] ルー,m] れし,m] れし,m] れし,m]
	Booms	☐ Trench	□ Dyke		
	Others:			<u></u>	
13.	Any pictures or v	rideo coverage?		[¥]	[N]
14.	Was there any di	sruption to the in	vestigation?	ſΆ	(N)

If yes give brief description:
THE INCLENT INVESTIGATION WAS DELAHED 21 AND 22 NO DETOBER 2011 DUE TO HIGH TIDE.
On 23 OCTORER, 2011 THE TIDE WAS LOW, THE PIPE WAS EXPOSED, THE CAUSE OF SPILL SEEN

BUT THE COMMUNITY REPRESENTATIVES DISAGREEDWITH THE CAUSE OF SPILL AND TOLD THE INCIDENT INVESTIGATION TOLERWE THE SITE. NO IMPACT D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL ASSESSIFMENT WAS BONE.

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	MARY				

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
		///				

17. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments

18. Others (Specify) i.e. Animal Traps

S/N	Others /	Description	Quantity/Size	Comments /
				//

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)

A SECTION OF 20" BUSUMA-ALAKIRI PIPELLUE AT BAKANA
SHOWING PUNCHED HOLE AT 3 O'CLOCK POSITION





Before plugging



After plugging

1

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0121 727743

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing	Easting
		,
		NO IMPACT ASSESSMENT WAS DONE DUE TO COMMUNITY DISTURBANCE, EXPA
		ASSESSMENT WAS
		DONE DUE TO COMMUNITY
<u>. </u>		DISTURBANCE, BOQ

20. Impacted Area Details BECKUSE THE COMMUNITY REPLEMENT THE COMMUNITY REPLEMENT THE COMMUNITY REPLEMENT THE LAWS OF SPILL AND TOLD THE IN	RESENTATIONS ABAGING
Total calculated area of impact Then To LENGE THE SITE	
Impact within SPDC R.O.W	
Impact outside R.O.W	_
21. Volume of oil recovered before completion of JIV (V _{ree} J):	Miles and a second a second and
Recovered oil V _{rec.} ; 31.5	barrels
20. Computation of the residual volume on site	
 a. Computation of volume of pool of free phase oil (on land or confined water body). i. Area (m²) occupied by pool of free phase oil 	
ii. Average Depth (m) of pool of free phase oil	<u> </u>
iii. Emulsification factor:	•
iv. Volume of pool of free phase oil. V _{pool} :	barrels

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

- b. Computation of volume of infiltrated oil in the soil (V_{inf}) .
 - i. Area (m²) covered by the oil: No IMPNET ASSESS MENT
 - ii. Area of the pool of free phase oil in touch with soil: WAS DONE DUE TO
 - iii. Average Depth (m) below ground surface of infiltration of oil: Community
 - iv. Soil type: 1) 15 TWR BANCE
 - v. P_e (effective porosity of the soil).___

iv. Volume of infiltrated oil. V _{inf}	barrels

- 21. Computation of volume of oil on open water based on standard coloration.
 - Total area of oil on open water:
 - ii. Table of average depth of oil on water based on coloration *

	Thickness (mm)	Percentage coverage	Volume (m3)	
Bareły Visible	0.00004			
Silvery	0.00008			
Slight Color	0.00015			
Bright Color	0.0003			
Dull	0.001			
Dark	0.002		· •	
Black oil	0.1			
Emulsion (30% Oil)	1			
	Percent Total	100%	Total Volume	bbl
	iii. Volume of o	l on open water. V***		barrels

iii. Volume of oil on open water. Vwiii	barrels

- 22. Calculation of evaporated volume:
 - i. Oil type:____
 - ii. E-Factor:

iii. Volume of evaporated oil V _{evap} :	barrels	1
---	---------	---

Evaporation Factors (E-Factor) for SPDC Crude oil				
Oil Type	Days on site	Bonny Light	Bonny Medium	
Period Since Oil Spill	< 1 day	10%	5%	
	1-7 days	25%	15%	
_	> 7 days	40%	25%	

23. Gross Total Estimated Spilled V	olume	$V_{Est}(bbls) = V_{evap}(bbls)$	\mathbf{S}) + \mathbf{V}_{wat} (bbls) + \mathbf{V}_{mf} (bbls) +
V_{pool} (bbls) + V_{recJ} (bbls)	•		
poor (=)			

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 121-127743

$V_{Est}(bbls)=$					
24. Net Total Estimated Spilled Volume V Est(bbls) = Vevap(bbls) + 0.6*Vevat (bbls) + Vinf (bbls) + Vpool (bbls) + Vrecl (bbls) VEst(bbls)=					
25. GENÉRAL STATUS OF THE SITE					
A. Joint investigation of the incident site found that there is no residual impact. After the initial response and therefore recommend that the site be closed out.					
B. Investigation of the incident site showed that there is residual impact on site requiring further works					
26 Signatories					
This report was filled and signed on the investigation representatives from					
• Host Community □					
• Department of Petroleum Resources [DPR]: ☑					
• National Oil Spill Detection and Response Agency [NOSDRA]:					
State Ministry of Environment [SME]: ✓					
Nigeria Police Force [NPF]:					
Shell Petroleum Development Company [SPDC]:					

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0121727743

20. Appendix 1: Overview sketch of the site

Location: 20" BUGUMA-ALAKIN PRELING AT BAKANA	
	/
· ·	
ŧ	



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0121 7277-43

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
<u> </u>		
	·	
_		
	No	IMPACT ASSESSMENT SONE DUE TO VITY DISTURBANCE,
	WAS I	one due to
· .	Commur Commur	VITY DISTURBANCE,
		a a
Z		