



Overview: Part of spill impact on 28 inch Trans Forcados Pipeline at Batan . Picture taken during Joint Investigation of 23<sup>rd</sup> September, 2011



Close-up: Spill due to External Corrosion on 28 inch Trans Forcados Pipeline at Batan. Picture taken during Joint Investigation of 23<sup>rd</sup> September, 2011.