



Overview: Part of spill impact on Batan Well 4T 6" Flowline at Batan. Picture taken during Joint Investigation of 12th September, 2011



Close-up: Spill due to corrosion on Batan Well 4T 6" Flowline at Batan. Picture was taken during Joint Investigation of 12th September, 2011