



Overview: Part of spill impact on ImoRiver III Well 1T flowline route at Ipu-West . Picture was taken during Joint Investigation of 14th and 15th September, 2011.



Close-up: Spill due to drilled hole on ImoRiver III Well 1T flowline at Ipu-West. Picture was taken during Joint Investigation of 14th and 15th September, 2011.