		ANT OF MIGERIA LIMITED
JOINT INVESTIGATION REP	ORT FOR INCIDENT N	10: 0103779129
(Note: As practicable as possible the JIT	report is to be signed in th	
A. GENERAL INFORMATION:	_	5 of the participating partiesy
1. Spill incident Number: 77912	9 2.Tvn	e of incident* All QPIII
3. Name of Location 18" ASS7	Y-Rumuel	CPE DIPELINE
4. Name of nearest community AWAR	CA 5. State:	MO GIGA OHATI-FGREMA
7. Type of Production facility/Installation	PIPELINE 8.	MO 6. LGA OHATI-EGBEMA SPDC Asset owner/District NPE / LAND 2
B. INCIDENT INFORMATION:		The state of the s
9. Details of incident a. Date of incident: 20TH Ft b. Date/Period of investigation: 21	EBRYARY 2	012 FERRUART 2012
c. Description of spill point environ	mont	100
Firmed soil	□ Loose soil	T Proviously
☐ Under water	□ Swampy	☐ Previously excavated area
□ Well Platform (on Water)	— эмширу	☐ Exposed pipe surface
d. Description of leak point (tick as	applicable);	□ Rig
☐ Drilled hole	☐ Hack saw cut	☐ Explosive tear,
☐ Complete Rupture	☐ Inward dent,	☐ Well head tampering
□ Failed Weld-on illegal hot tap		☐ Missing Pipeline/Flowline)
☐ Crude oil theft (illegal bunkeri		☐ Third party tampering with Clamp
☐ Third party tampering with val	ve setting,	☐ Third party tampering with flange,
☐ External Corrosion		☐ Internal Corrosion
☐ Saver-pit over flow,	☐ Surge vessel overflow	
☐ Flare System/Bund wall Failur		C com unit failure
□ Cold vent	☐ Relief valve failure	Others (specify) CLAMP FAILUR
e. Incident due to:		· · · · · · · · · · · · · · · · · · ·
☐ Third party interference	• Operational	□ Others (specify
f. Spill point coordinates Measuring unit (METER)	MINNA MI)-BELT
Northing:	To the latest to	Easting:
149379.7	6	481717.41
149379.17	}	481717.24
149377.31	6	481716.70

Page 1 of 9

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0103 77 9129

C.	RISK ASSESSME	NT				
	10. Type	of environment:		.3		
	Land	□ Swamp	□ Water	□ Seasonal sv	vamp	
	i. Type o	f environment to	which oil has sp	read:		
	Land	□ Swamp	□ Water	☐ River (iden	tify) NO 7	MPP LI CHELE
	ii. Weathe	r condition				
	☐ Raining 11. Distance from the	Sunny ne nearest sensiti	ve habitat			
	Governmen Governmen Grinking wa Built up are Farmlands Fish Farm/F Governmen Fishing net Others (spec	ond Aff	NOT PLICA	BLE [,m] ,m] ,m] ,m] ,m]	
	□ Booms	french	□ Dyke			
	Others:			· 12.		
	13. Any pictures or	video coverage?		M	[N]	
	14. Was there any di	isruption to the in	vestigation?	[Y]	ØN.	
If y	es give brief description	on:				
	MOT	API	PLIC	ABLE		

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	NONE	HAITH	HN	AREA	OF IMPACT
	140110	 	, , , ,		

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0103779129

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
1	YONE	WITHIN	ARE	A OT	IMP	Aet

17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
N	ONE WI	FHMARER	07 IN	MACT


18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/S	Size Comments
			<u> </u>	
$+\mathcal{M}$	ME	WITHIN #	tret of	Impact
, ,		7 4 7 1 7 7	•	1,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)

A SECTION OF 12" ASSA - RUMUEKPE PLPELINE AT

AWARA SHOWING THREE CLAMPS LEAKING AT 6 0" CLUCK
POSITION



JOINT INVESTIGATION REPORT FOR INCIDENT NO:

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION .

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

)-BZL1
Northing (METER)	Easting (METER)
149379.61	481719.57
149376.53	481722.64
149364.23	481725.69
149367,34	481713.38
149379.62	481713.41
149382.69	481716.50
11/2	
0.0111	
brea.	
	149376·53 149364·23 149367·34 149379·62

G. INCIDENT INFORMATION:

\sim	T	. 1	•	-	•
70	Imna	cted	Area	Detail	c
	MATTER		4 M C U	- LUMI	

- 10	iai calculated area of impact		1 (194	
• Im	pact within SPDC R.O.W	10.01	Ha	
• Im	pact outside R.O.W	NIL		
21. Volume of	oil recovered before completion	n of JIV (V _{rec.J}):		
	Recovered	oil V _{rec.J} :	NUL	barrels
20. <u>Computation</u>	on of the residual volume on site	2		
a. Computation	n of volume of pool of free phase of	il (on land or confi	ned water body).	
	Area (m²) occupied by pool of fre		<u> </u>	
ii.	Average Depth (m) of pool of free	e phase oil	MAL	
iii.	Emulsification factor:	AL.		
	iv. Volume of pool of free	nhasa oil 17	A 1	barrels

0.014

		•	PANY OF NIGERIA LIMI	
JOINT INVE	STIGATION REP	ORT FOR INCIDENT I	NO: 0173 719	1129
b. Computation	of volume of infilt	rated oil in the soil (V_{inf}) .		
	i. Area (m²) cov	ered by the oil:	147	
		ol of free phase oil in tou		
			ce of infiltration of oil: 0-	02
	iv. Soil type:	char!	057	
	v. $P_{\rm e}$ (effective p	porosity of the soil)	8%	
	iv. Volume o	of infiltrated oil. Vinf	1:5	barrels
i. Total area	Thickness (mm) 0.00004 0.00008 0.00015 0.0003 0.0001	on open water based of NAL on water based on coloration water based on coloration coverage		
Emulsion (30% Oi	-			MIL hou
	Percent Total	100	9% <u>Total Volume</u> ী	bbl bbl
	iii. Volume of oi	l on open water. Vwat:	NOT	barrels
	of evaporated vol			
i. Oil	type: BONN	y Licity		
ii. E-F	type: BOMN actor: 25%	<u>o</u>		
Ţ	iii. Volume of ev	aporated oil. V evap:	0.5	barrels

Evapor	ration Factors (E-Fa	actor) for SPDC Crud	le oil
Oil Type	Days on site	Bonny Light	Bonny Medium
Period Since Oil Spill	< 1 day	10%	5%
	1-7 days	25%	15%
	> 7 days	40%	25%

23. Gross Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls) = 0.5 + ML + 1.5 + ML + ML = 2BARLETS$

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0103749129

V _{Est} (1	obls)= 2 BARKELS
2	4. Net Total Estimated Spilled Volume V _{Est} (bbls) = V _{evap} (bbls) + 0.6*V _{wat} (bbls) + V _{inf} (bbls) +
	Vpool (bbls) + VrecI (bbls) = 05 fruit #1.5+ ML-fruit = 2 BARKE
VEst	(bbls)=
^k Conve Emul	elation of the respective estimated volume is to be done using the new spill estimation software on site ersion of m3 to barrels is Total volume VT (m3) x 6.29 sification factor for spill on water to consider is 60% of volume of oil. 5. GENERAL STATUS OF THE SITE
A.	Joint investigation of the incident site found that there is no residual impact. After the initial response and therefore recommend that the site be closed out □
R	Investigation of the incident site showed that there is residual impact on site requiring

26 Signatories

further works


This report was filled and signed on the 25/20/20 at incident site by joint investigation representatives from

- Host Community
- Department of Petroleum Resources [DPR]: \Box
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]:
- Shell Petroleum Development Company [SPDC]:

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0103 779129

20. Appendix 1: Overview sketch of the site



THE SHELL PETROLEUM DEVELOPMENT COMPANY OF	NIGERIA LIMITED
JOINT INVESTIGATION REPORT FOR INCIDENT NO:	0103
JOINT INVESTIGATION REPORT FOR INCIDENT NO:	

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
		