#### THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED 0192 JOINT INVESTIGATION REPORT FOR INCIDENT NO: (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 2.Type of incident\* OIL SPILL 3. Name of Location \_\_\_\_\_6\*\* OBIGBO NORTH PIPELINE 4. Name of nearest community OGALE 5. State: RIVERS 6. LGA FLEME 7. Type of Production facility/Installation PIPELINE 8. Asset owner/District NPE/PH | **B. INCIDENT INFORMATION:** 9. Details of incident a. Date of incident: 1ST FEBRUARY 2012, b. Date/Period of investigation: 3RD FEBRUARY, 2012 c. Description of spill point environment Firmed soil Previously excavated area □ Loose soil ☐ Under water □ Swampy ☐ Exposed pipe surface ☐ Well Platform (on Water) □ Rig d. Description of leak point (tick as applicable); □ Drilled hole ☐ Hack saw cut □ Explosive tear, ☐ Complete Rupture □ Inward dent, ☐ Well head tampering Failed Weld-on illegal hot tap valve, ☐ Missing Pipeline/Flowline) ✓ Crude oil theft (illegal bunkering) point, ☐ Third party tampering with Clamp ☐ Third party tampering with valve setting, ☐ Third party tampering with flange, □ External Corrosion □ Internal Corrosion □ Saver-pit over flow, □ Surge vessel overflow, □ Outward dent ☐ Flare System/Bund wall Failure ☐ Valve Failure □ com unit failure □ Cold vent □ Relief valve failure □ Others (specify) e. Incident due to: Third party interference □ Operational □ Others (specify f. Spill point coordinates MUNTA MUD BEL Measuring unit Northing: (m) 521361.25

Page 1 of 9

90765.44

<sup>\*</sup>This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

				COMPANY OF NIGERIA LIMITED	
	JOINT INVEST	GATION REPO	ORT FOR INCID	ENT NO: 0192-771945	
C.	RISK ASSESSMEN	T			
	10. Type of	environment:			
	Land	□ Swamp	□ Water	□ Seasonal swamp	
	i. Type of e	environment to v	which oil has sprea	ıd:	
	Land .	□ Swamp	□ Water	□ River (identify)	
	ii. Weather	condition			
	☐ Raining .  11. Distance from the	Sunny nearest sensitive	e habitat		
	☐ Government in☐ Drinking water ☐ Built up area ☐ Farmlands	reserved and des er source	ignated protected	area [ ,m] [ ,m] [ ,m]	

☐ Others (specify).

12. Containment measures put in place;

☐ Fish Farm/Pond

☐ Fishing net

□ Booms	Trench	□ Dyke
---------	--------	--------

Others: NATURAL DEPRESSION.

13. Any pictures or video coverage? [Y] [N]

14. Was there any disruption to the investigation?

[Y] [N]

,m]

If yes give brief description:



# D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	ONE V	VITHIN	ARE	A OF	IMPACT

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0192771945

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
			A		•	
$\square$	MIT	1 d / Tun	$\Lambda_{\Omega}$	7	NOAS	
	UINE	VVIIHIN		力して	IMPAL	- 1 .
,						


17. Fish/Nets/Ponds

S/N	Fish/Nets/P	onds	Description		Quantity/Siz	ze	Comments
		111		Λ			
$\Gamma \Gamma \Gamma$		$\Lambda \Lambda I$ 1	MIN	ADE			7
$\Pi M$		<u> </u>	I ITHY	いいして		יין	ことし
	7 7						

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	n	Quantity/Siz	ze	Comments
No	NE	WITHIN	AREA	OF	N	IPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0192771945

#### F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

	Larry 4 property	20-12
S/N	Northing Cm)	Easting Cm
676	90728.72	521293.29
679	90737.94	521290.32
681	90756.37	521290.36
682	90759 . 45	521284.20
684	90762.53	521284.21
685	90768 67	521281.14
686	90768.66	521287.30
687	90765 58	521290.38
688	90762-52	521287-29
689	90759 . 44	521290.37
690	90771.72	521293-47
691	90768·64	521296.55
692	90765.57	52-1296.54

#### G INCIDENT INFORMATION:

20	Impacted	Area	Det	aile
ZU.	HIIDACICU	ALCA	リノにし	aus

• Total calculated area of impact 0.17#4		_
Impact within SPDC R.O.W		
Impact outside R.O.W		_
21. Volume of oil recovered before completion of JIV (V <sub>rec</sub> J):		
Recovered oil V <sub>rec</sub> r.	19	barrels
20. Computation of the residual volume on site		
<ul> <li>a. Computation of volume of pool of free phase oil (on land or confi</li> <li>i. Area (m²) occupied by pool of free phase oil</li> </ul>	ned water body).	<u> </u>
ii. Average Depth (m) of pool of free phase oil	0-014	_
iii. Emulsification factor:		
iv. Volume of pool of free phase oil. V <sub>pool</sub> :	61.64	barrels

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0192 771945

- b. Computation of volume of infiltrated oil in the soil (V<sub>inf</sub>).
  - i. Area (m²) covered by the oil:
  - ii. Area of the pool of free phase oil in touch with soil:
  - iii. Average Depth (m) below ground surface of infiltration of oil: 0.025
  - iv. Soil type: \_\_CLAY
  - v.  $P_{\rm e}$  (effective porosity of the soil).

iv.	Volume of infiltrated oil. Vinf	21.39	barrels

- 21. Computation of volume of oil on open water based on standard coloration.
  - i. Total area of oil on open water:
  - ii. Table of average depth of oil on water based on coloration \*

	Thickness (mm)	Percentage coverage	Volume (m3	3)	
Barely Visible	0.00004				
Silvery	0.00008				
Slight Color	0.00015				
Bright Color	0.0003	1 40-1			
Dull	0.001	A			
Dark	0.002	ADDI 10	ARIL		
Black oil	0.1	TILLE			
Emulsion (30% Oil)	1				
	Percent Total	100%	Total Volume	NIL	bbl

iii. Volume of oil on open water. Vwat:	NIL	barrels

- 22. Calculation of evaporated volume:
  - i. Oil type: BONNY MEDIUM
  - ii. E-Factor: 15%

iii.	Volume of evaporated oil. V evap:	10 -	barrels
	volume of evaporated off. v evap.	18-01	Journell

Evaporation Factors (E-Factor) for SPDC Crude oil				
Oil Type	Days on site	Bonny Light	Bonny Medium	
Period Since Oil Spill	< 1 day	10%	5%	
	1-7 days	25%	15%	
	> 7 days	40%	25%	


23. Gross Total Estimated Spilled Volume  $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls) = 18 \cdot 01 + NIL + 21 \cdot 39 + 61 \cdot 64 + 19 = 120 \cdot 04$ 

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0192771945

V <sub>Est</sub> (bbls)= 120 RACOEI C
TAU DAINCERS.
24. Net Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + 0.6*V_{wat}(bbls) + V_{inf}(bbls) + $
$V_{pool}$ (bbls) + $V_{recJ}$ (bbls) = 18.01 + NL+ 21.39 + 61.64+19 = 120.04
VEst(bbls)= 120 BARRELS.
*Calculation of the respective estimated volume is to be done using the new spill estimation software on site
*Conversion of m3 to barrels is Total volume VT (m3) x 6.29
*Emulsification factor for spill on water to consider is 60% of volume of oil.
25. GENERAL STATUS OF THE SITE
A. Joint investigation of the incident site found that there is no residual impact After the
initial response and therefore recommend that the site be closed out □
B. Investigation of the incident site showed that there is residual impact on site requiring
further works 🗔 .
26 Signatories
This report was filled and signed on the <u>03/62/2012</u> at incident site by joint investigation representatives from
• Host Community   DPR INCIDENT
• Department of Petroleum Resources [DPR]: ATTACHED
• National Oil Spill Detection and Response Agency [NOSDRA]:
State Ministry of Environment [SME]:
Nigeria Police Force [NPF]:□
Shell Petroleum Development Company [SPDC]:
Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 77194

20. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: U192771945

# 21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION MAINTA MAD 15-LT

		THE POLI
S/N	Northing (M)	Easting (M)
693	90759.42	521299-61
694	90756-32	521315.01
695	90756. 25	521398.91
704	90774.68	521352-03
702	90774.71	521336.62
70(	•	521324.30
750	90783.94	521380. 47
699	90780.83	521345.87
698	90180.82	521352.04
647	96793. 1	52(352 · 66 52(355 · 20
697 796 723 768 709	9 6793 · 11 9 6823 · 82 9 6854 · 53 9 6872 · 95	521868 · 43 521364 · 55
709	90872 · 94 90857 · 59 90858 · 52 90826 · 74 90786 · 95 90790 · 52	£3-1367 · 63
760	90829 . 52	521864. 51 54361. 36
711 713 714	90786 - 95	521364 · 56 521358 · 36 521361 · 36
415	90786 - 95 90790 : 52 90762 : 37 90762 : 37	S21364. 33
667 673 674	90762 · 37 90728 · 61 90728 · 61 90753 · 18 90753 · 28 90756 · 35	251348 · 90 251348 · 90 251348 · 90
673	90753 . 28	521321: 17
	90756.36	521293 44
	<u> </u>	<u> </u>

## **DEPARTMENT OF PETROLEUM RESOURCES**



## OIL /CHEMICAL SPILL INSPECTION REPORT

Al Company SPDC Blank Incident No 771945
A) Company:  1. Facility/Location:  A) Company:  B) Spill Incident No. T. F. T.
2. Date/Time Observed: 01-02-2012. 3.Date of JIV: 03-02-2012.  4. Known extent of pollution/Impact:  (1) SPDC RIGHT-OF-WAY  (2) IHTRO PARTY FARMLANDS  5. Precautionary measures taken to prevent Hazard/ further pollution since the spillage/leakage occurred:
(a) [] Bundwalls (b) [] Booms (c) [] Sorbents (d) Others (Specify): CONTAINMENT PITS
6. Cause of Spill:  Drilled Hole Explosive tear Inward Dent Failed Weld Acid Induced Corrosion Saver Pit Overflow Blasting Third Party tampers with clamp Operator/Maintenance Error Others (Specify)  Hack Saw Cut Inward Dent Crude Oil Theft (Illegal Bunkering) Natural Corrosion Surge Vessel Overflow Blowout Third party tamper with: valve, Bolt, Nuts Equipment Failure
7. Estimated Quantity Spilled (bbls):  (a) Detailed Calculations: (attach additional sheets if necessary)  8. Operational Area  (i) OPL/OML No/UNIT DESCRIPTION
11. Weather Conditions:  (a) Bright and Sunny (b) Cloudy (c) Rainy (d) Others Specify (e) Wind Direction (h) Wind speed (g) Not Applicable

12. Sea Conditions				
(a) Calm (b) Rough (a) Not Applicable				
(Others (Specify)				
(d) Direction of current:				
(d) Direction of current:				
(// =				
(g) Tidal Condition: High Low				
13. Quantity of Crude Oil/Contaminant Recovered as at Time of Reporting:				
14. Any casualties: (a) Yes (b) No				
If yes give details:				
15. Steps taken to clean-up the spilled oil:  CRUDE OT HOUSE OF HOUSE  16. Chemical/ Dispersants Used: Yes No DPR Approved: Yes No (a) Type: (b) (b) Quantity: (c) (c) Not applicable: (d) (d) Others (Specify): 17. Any Fire Incident: (a) Yes (b) No (c) If Yes, Give Details:				
18. Attachments: Maps Others: Pictures				
19 Pacammandations of the Investigation				
19 Recommendations of the Investigation:  HELINE AND				
CITA-13-1970 ENERGY THE TAXABLE TO THE				
CLEAN-UP / REMEDIATE THE IMPACTED AREAS.				