



Overview: Part of spill impact on 28" Bomu-Bonny pipeline at K-Dere. Picture was taken during Joint Investigation of 9th May 2012.



Close up: Leak point, due to corrosion, at 6 o' clock position on 28" Bomu-Bonny pipeline at K-Dere. Picture was taken during Joint Investigation of 9th May 2012.



Close up: Leak point, due to corrosion, at 6 o' clock position on 28" Bomu-Bonny pipeline at K-Dere. Picture was taken during Joint Investigation of 9th May 2012.