



Close up: Missing bolts on Imo River2 Well28L flowline at Umuedeokwara. Picture was taken during Joint Investigation of 26th May 2012.