		MPANY OF NIGERIA LIMITED
JOINT INVESTIGATION REPO	ORT FOR INCIDENT N	10: <u>0:115 - 8947 53</u>
(Note: As practicable as possible the JIT re		
A. GENERAL INFORMATION:		
1. Spill incident Number: 89479	5 <u>2.</u> Typ	e of incident * CTL SPILL
3. Name of Location Mb KIVEC	WART PARIT	FLOWLINE
4. Name of nearest community <u> </u>		1819 6.LGA UKNIA NIBST
7. Type of Production facility/Installation	PIPELINE 8.	Asset owner/ District NESP LAND
B. INCIDENT INFORMATION:		
a. Date of incident: 16 Th Novice b. Start date/time of investigation: 2 c. Investigation End date: 23 h Novice d. Description of spill point environs    Firmed soil     Under water     Well Plateform (on Water) e. Description of leak point (tick as a     Drilled hole     Complete Rupture     Failed Weld-on illegal hot tap     Crude oil theft (illegal) banker     Third party tampering with val     Corrosion     Outward dent     Valve Failure	AND NEUTONESS, CONTROL OF THE CONTRO	Previously excavated area  Exposed pipe surface  Rig  Explosive tear,  Well head tampering  Missing Pipeline/Flowline)  Third party tampering with Clamp  Third party tampering with flange,  Surge vessel overflow
Relief valve failure	Others (specify)	<u> </u>
f. Incident caused by:  Third party interference	Operational	Mystery
g. Spill point coordinates  Measuring unit (MCC)	(WINNY O	MID-BEIT
Northing:		Easting:
10849	3.49	524095.66

Page 1 of 9

### THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: C. RISK ASSESSMENT 10. Type of environment: □ Laπd □ Swamp □ Water Scasonal swamp Type of environment to which oil has spread: Land □ Swamp □ Water ☐ River (identify) ii. Weather condition □ Raining USunny 11. Distance from the nearest sensitive habitat ☐ Government reserved and designated protected area ,m] ☐ Drinking water source ,m] ☐ Built up area ,m] ☐ Farmlands .m] ☐ Fish Farm/Pond ,m) ☐ Fishing net ☐ Others (specify). 12. Containment measures put in place; ☐ Booms ☐ Trench □ Dyke NATUKALLY CON (MINES IYI (NI 13. Any pictures or video coverage? 14. Was there any disruption to the investigation? If yes give brief description: D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

ľ

### 15. Structures / Properties

S/N Type of Structures	Description	Size	Number	Comments
NONE	HITHIR	<b>1</b> X	CEA OF	MPACT

JOINT INVESTIGATION REPORT FOR INCIDENT NO; 0415-8947 53

### 16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	Nano	1114	X IA	C 4	1)	ADICT -
	1 ACIME	Milit	114 -77	my	<del>- 1</del>	JANG !

### 17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
<b>\</b>	18310	A		
<del>   \</del>	M APOP	<del>!                                    </del>	<del></del>	
<del>                                     </del>				V V


18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	ENE	WITHIN	AREA OF	MPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1)

SECTIONAL SKETCH OF IMP RIVER WELL 645 FLOIDLINE AT CHAZA

### SHOWING MUSING FLUSHINE



## 

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION
19. Impacted area boundary, Coordinates (If more than 12 points, Attach as an appendix 2)

	(MINHA M	1) - BEIT)
S/N	Northing (METER)	Easting (METEC)
W677	108 462 - 91	524 027.83
W6028	108475.24	524 006.29
<u> </u>		
		, ·
ļ		,
<u> </u>		
ļ. <u>.</u>		
_		

### G. INCIDENT INFORMATION:

20.	Impacted	l Area	Details

	Total calculated area of impact Impact within SPDC R.O.W Impact outside R.O.W	56 Ha Yes Yes	_ 
21.	Volume of oil recovered before completion of JIV	(V <sub>rect</sub> ):	
	Recovered oil V <sub>met</sub>	CHGCING	barrels
20. a.	Computation of the residual volume on site  Computation of volume of pool of free phase oil (on lar  i. Area (m²) occupied by pool of free phase	nd or confined water body).	

THE SHELL PE	TROLEUM DI	EVELOPMENT C	OMPAI	NY OF	NIGERIA LIMITED	
JOINT INVES	STIGATION REF	ORT FOR INCIDE	NT NO:		1415 - 89475	> 5
		3c <sup>℃</sup> /⊾	•			
iii. Emulsification	lactor:					
iv.	Volume of	pool of free phase oil	V <sub>pool</sub> :	_	466.72	barrels
h Commutation	of maluma of infile	rated oil in the soil (	(7 \ \			
b. Computation of The are in the computation of the are in the computation of the computa		rated on in the son ( evered by the oil:	V inf)-	114	1990 · CD	
Jula 7. or strate		-				
Compulation of the or i	"	ool of free phase oil i				
- 1 51° - 2	ii Average Dept		surface o	f infiltra	tion of oil: CC5	
rolling to the			₹:	٠٠,		
DEPT = 15M . 1. 55 bb 1	P <sub>e</sub> (effective	porosity of the soil).		76	<del></del>	
Dero 17 10 1 55 to 18 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	v. Volume (	of infiltrated oil. V	ıſ		37.71	barrets
Yes 21 Communication	-6l		-44		1	
21. Computation	of volume of oil of oil on open wate	on open water bas	ca on st	andard (	coloration.	
ii. Table of ave	•	n water based on color	ation • •			
					*	
	Thickness (mm)	Percentage coverage	•	Vo	lume (m3)	
Barely Visible	0.00004	3373,33				
Silvery	0.00008					
Slight Coior	0.00015	1.1.	<b>)</b>			
Bright Color	0.0003	140	1			
Duli	0.001	100	n(	<i>(</i>	<del></del>	
Dark	0.002	77	アド	CAL	> <del> -  </del>	
Black oil	0.1	<u> </u>				
Emulsion (30% Oil)	_1	<u> </u>				$\neg$
	Percent Total		100%	Tota	al Volume NUL 1	144
· tii.	Volume of o	il on open water. V	MUNT:		NIL	partels
22. Calculation of	of evaporated vo	lume:	-			
i. Oil 1	ype: Benny	MEDUM				
		<del></del>				
ii. E-F	actor: 15 %	3				
ìii. Г	Volume of e	vaporated oil. V pvap:			90 35	barrels
L					19 30	
Evapora	tion Factors (E-Fac	tor) for SPDC Crude	oil			
Oil Type	Days on site	Bonny Light	Bonny Medium	,		
Period Since Oil	< 1 day	10%	5%			

Evaporation Factors (E-Factor) for SPDC Crude oil					
Oil Type	Days on site	Bonny Light	Bonny Medium		
Period Since Oil Spill	< 1 day	10%	5%		
	1-7 days	25%	15%		
	> 7 days	40%	25%		

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 23. Gross Total Estimated Spilled Volume  $V_{\text{Est}}(bbls) = V_{\text{evap}}(bbls) + V_{\text{wat}}(bbls) + V_{\text{inf}}(bbls) + V_{\text{pool}}(bbls) + V_{\text{recl}}(bbls)$ VER(bbls)- 90 35+ AIL + (755+ 37 71)+ 466 12+ NIL = 602 35 BARRELS 24. Net Total Estimated Spilled Volume  $\mathbf{V}_{\text{Est}}(bb|s) = \mathbf{V}_{\text{even}}(bb|s) + 0.6 \mathbf{V}_{\text{wat}}(bb|s) + \mathbf{V}_{\text{even}}(bb|s) + \mathbf{V}_{\text{post}}(bb|s) + \mathbf{V}_{\text{post}}(bb|s)$ VESTIBBLE 603 BARROGS. \*Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site \*Conversion of m3 to barrels is Total volume VT (m3) x 6.29 \*Emulsification factor for spill on water to consider is 60% of volume of oil. 25. GENERAL STATUS OF THE SITE A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out [ B. Investigation of the incident site showed that there is residual impact on site requiring further works **26 REPRESENTATIVES** 23 / 11 /20 12 at incident site by joint This report was filled and signed on the investigation representatives from Host Community 

✓ • Department of Petroleum Resources [DPR]: ☑ • National Oil Spill Detection and Response Agency [NOSDRA]: State Ministry of Environment [SME]: □

• Nigeria Police Force [NPF]:□

• Shell Petroleum Development Company [SPDC]:

. Page 6 of 9

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 6115-894753

27. Appendix 1: Overview sketch of the site

Location: Mu Ruse k	lerr 645	FLOWLING	<b>~</b> 7	
1/1/1/		Spik P	เมา	SAL
ne fre		•	V	No Park
	Non-us		,	mpact 441 m
Buom	pedrated	l. 0		<b>YY</b>
94///		lme Riv Well Gi		
JAN Y.	r 4 4	1 Pandy		- Tare
	1	IT UT IN	)	* **
The Market	THICK Y	1 7 7		4 80 1
A .	4 Bysit	1 4 4 7	1-1	1
1 / S 1	' 'Y 1 1	1 1	1 1 . -1	
	/ * 1, 4	I IMPAC	, ¥	<b>+</b>
$\frac{1}{2}$				
SPULTIN	· Heav	F ' 1 ' ' '	P*-34 /	
/	. A traite	INT	buck	
SETTLEMENT	1/-/	4 4 7	Si.	
POINT:	1 : 14	1 1	Y	
MATULE:	THYPOLIC	1 Imo KINER	/	
DEPRESSION	* Bush	1 CONSTRUCTO	Y	
, + \ 4 "	1	[ ]	CM	
	4 1	Y SITE	ŧ	`~
No Assured	· · · · · · · · · · · · · · · · · · ·		<del></del>	· -···
DRAMAGE:     TAG	ekeb Rom	, — —		
impact.		. 7		
			<u>.</u> ,	
Impacted Area Within Right of	Imo River	WELL 255 FLOW	INE S	Spill Site
MULLIN KIGHT OF				·

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0415 - 894753

# 21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

MID - BEIT) (MINNA S/N Northing Easting (NETER) (METEZ) 108 481.65 W1968 523 873 83 523 833 71 W9069 108 444.87 WPOTE 108 429.59 523 793 63 W1053 108 429.61 523 781-31 W054 108448.12 523741.29 108 491.10 523756.78 WP057 108512.57 NP061 523772.23 WP063 523778.40 108518.70 108 533 95 523830 81 NP 066 108684.54 WP080 523797.22 108687.57 W1081 523815.71 523880 07 WP067 108521.57 W1085 108498.25 524084.82 108 554 66 524090.65 W086 w/087 108 553.69 524102.32 W1072 524104.76 108422.82 524077.05 WP075 108 432.09

108 450.56

W 076

52405861