



Close-up: Submerged location of corrosion on Bonny Well 2S Flowline at Bonny. Picture was taken after retrieval of failed section.