



Close up: Spill point due to corrosion on 24" Bomu-Bonny Trans Niger pipeline at Freetown. Picture was taken during Joint Investigation of 5<sup>th</sup> October 2012.