



Overview: Part of spill impact on Opukushi Well 25 at Agbediama. Picture was taken during Joint Investigation of 13th Sept. 2012.



Close-up: Internal corrosion on Opukushi Well 25 at Agbediama. Picture was taken during Joint Investigation of 13th Sept. 2012