THE SHELL PETROLEUM D	EVELOPMENT COM	PANY OF NIGERIA LIMITED
JOINT INVESTIGATION REPO	RT FOR INCIDENT NO:	0352/866164
(Note: As practicable as possible the JIT re	port is to be signed in the	field by all the participating parties)
A. GENERAL INFORMATION:		
1. Spill incident Number: 86616		
3. Name of Location IMURIVER	WELL 33	5L FLOWLINE
4. Name of nearest community Name of nearest community	ZA 5. State: AB	1A 6.LGA LIKINU- WEST
7. Type of Production facility/Installation	-LOWLINE 8. AS	iset owner/ District NELI/PHZ
B. INCIDENT INFORMATION:		
a. Date of incident b. Start date/time of investigation: c. Investigation End date:	LTH SEPTEMBER Premier 2012 ent	_,2012
Firmed soil	Loose soil	☑ Previously excavated area
Under water	USwampy	Exposed pipe surface
Well Plateform (on Water) e. Description of leak point (tick as a)	pplicable);	□Rig
Drilled hole	□Hack saw cut	☐Explosive tear.
Complete Rupture	☐ Inward dent,	☐ Well head tampering
Failed Weld-on illegal hot tap v	/alve,	☐ Missing Pipeline/Flowline)
Crude oil theft (illegal) bunkeri		☐ Third party tampering with Clamp
Third party tampering with val	ve setting,	☐ Third party tampering with flange,
Corrosion	Saver-pit over flow.	☐ Surge vessel overflow
Outward dent	Flare System/Bund wa	
□Valve Failure	com unit failure	☐ Cold vent
Relief valve failure	Others (specify)	 _
f. Incident caused by:		
☑Third party interference	☐Operational	□ _{Mystery}
g. Spill point coordinates Measuring unit	llinna - [Mid b	elt) (m)
Northing: (m)	, la	Easting:
108301.34	6	526482.784

Page 1 of 9

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 3332/866164 C. RISK ASSESSMENT 10. Type of environment: M Land □ Water □ Swamp □ Seasonal swamp Type of environment to which oil has spread: ☑ Land □ Swamp □ Water ☐ River (identify) ίį. Weather condition Sunny □ Raining 11. Distance from the nearest sensitive habitat □ Government reserved and designated protected area ☐ Drinking water source NOT APPLICABLE ☐ Built up area .m]☐ Farmlands .mI ☐ Fish Farm/Pond m☐ Fishing net ☐ Others (specify). 12. Containment measures put in place; □ Booms ☐ Trench □ Dyke Others: NATURAL COMTAINMENT 13. Any pictures or video coverage? [N]14. Was there any disruption to the investigation? [Y] If yes give brief description: D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL.

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	31.00	1 501			
	\\\(\(\(\)\\\\\\\\\\\\\\\\\\\\\\\\\\\\	APPLIC	CABL	<u> </u>	
	/ / /	11 7 .			
			 	 	

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	A 1			·		
	- N/ 07	APPH	CAKI			
	- 4 - 2 - 7	/ \ 	<u> </u>			

17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	N 1 /		<u> </u>	
1	NOT	APPII (A	K/ = -	-
<u> </u>	14 0	7111/10/1	D	


18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	MATA	DDILCADI	Γ	
	N UI _ P	ITLILADA	<i>L</i>	
	, , , , , , , , , , , , , , , , , , , ,		_	

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1)

A SECTION OF IMPRIVER WELL 33L FLOWLINE AT OWAZA SHOWING

I" VALVE CLAMPED ON THE 4" FLOWLINE AT 3 D'CLOCK POSITION



THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0352/86/64

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

	Minna - M	ich beit
S/N	Northing (M)	Easting (N1)
WP139	108361.346	526442-784
WP 140	108307.502	526476 635
NP 142	108 307 477	526489 957
NP 143	108 301 334	526 488. 945
NP 141	108247.671	526 479 710.
	£	
		3
	·····	

G INCIDENT INFORMATION:

	Total calculated area of impact Impact within SPDC R.O.W Impact outside R.O.W Total calculated area of impact Total calculated ar	
21.	Volume of oil recovered before completion of JIV (V _{recI}):	
	Recovered oil Viest	barrels
20.	Computation of the residual volume on site	
8.	Computation of volume of pool of free phase oil (on land or confined water body). i. Area (m²) occupied by pool of free phase oil	

				NY OF I	NIGERIA LIMITE	E D Z. J.
	Alr:	ORT FOR INCIDE	ENT NO	·	78661	<i>64</i>
iii. Emulsification	factor:					
iv.	Volume of	pool of free phase oi	I. V _{pool} :		NI-	barrels
b. Computation	of volume of intilt	rated oil in the soil	(V).			
THE BLIDE OF VOLUME :	A */2\	vered by the oil:	``""\8:	t.9		
TIMPLETRATION OF SPILL PENT	i Area of the no	ool of free phase oil		with soil:	N ₁	
DEPTH = D.5M	ii Average Dent				ion of oil: <u>C +QC</u>	-
or - 177 - 2 1 days	v Soil type:		Surface	or minuras	ion of off; <u>C 24/C.</u>	<u> </u>
Para recent = 8/2		- -	03			
1x0.5x.00x629		porosity of the soil)			-	
-> 0.25 BARRELS	v. Volume o	of infiltrated oil. V	Int O	25+ (0.13 = 0.32	Name la
	of volume of all	on open water ba			-	
_	of oil on open wate	_	seu on s	tandard (oloration.	
il. Table of ave	-	n water based on colo	ration	- ·		
	•					
	Thickness (mm)	Percentag coverage	•	Voi	iume (m3)	
Barely Visible	0.00004		<u> </u>		(1110)	1
Silvery	0.00008					1
Slight Color	0.00015					1
Bright Color	0.0003	NOTA	וממ	(/ A	77 i i]
Dull	0.001	NUI_A	PPL	$I \cup H$	BLE]
Dark	0.002			, , , , , , , , , , , , , , , , , , ,		
Blackoil	0.1					
Emulsion (30% Oil)	1				··-	<u> </u>
	Percent Total		100%	Tota	il Volume	bbl
iii.	Volume of o	il on open water. \	Vwaz:		116	barrels
22. Calculation of	of evaporated vo	lume:				
i. Oil	ype:BONNY	MEDIUM				
ii. E-F	actor: 15 /					
iii.	Volume of e	vaporated oil V	: 1		-07	berreis
L					- U 	
Evapora	tion Factors (E-Fac	ctor) for SPDC Crude	oil			
Oil Type	Days on site	Bonny Light	Bonny			
	 	100/	Mediu			
Period Since Oil Spill	< 1 day	10%		%		
	1-7 days	25%	1 1:	5% 🗸		

40%

25%

> 7 days

^{*}If area is not same as the total area of impact, please indicate in the overview sketch ** Spill Factor from USCG FOG (2000 Edition)

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0352 866 64


25. Gross lotal Estimated Spilled Volume
$\mathbf{V}_{\text{tot}}(hbls) = \mathbf{V}_{\text{evap}}(bbls) + \mathbf{V}_{\text{var}}(bbls) + \mathbf{V}_{\text{tot}}(bbls) + \mathbf{V}_{\text{peak}}(hbls) + \mathbf{V}_{\text{peak}}(bbls)$
V. (106) 0. 07 + NIL + D.38 + NIL + NIL = 0.5 BBLS
24. Net Total Estimated Spilled Volume
$V_{1st}(bbls) = V_{evap}(bbls) + 0.6*V_{wat}(bbls) + V_{int}(bbls) + V_{post}(bbls) + V_{rect}(bbls)$
VEST(Bbls) - 0.07 + NIL + 0.38 + NIL + NIL = 0.5 BBLS
*Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site
*Conversion of m3 to barrels is Total volume VT (m3) x 6.29 *Emulsification factor for spill on water to consider is 60% of volume of oil.
25. GENERAL STATUS OF THE SITE
A. Joint investigation of the incident site found that there is no residual impact after the
initial response and therefore recommend that the site be closed out
B. Investigation of the incident site showed that there is residual impact on site requiring
further works
26 REPRESENTATIVES
This report was filled and signed on the 14/04/2012 at incident site by joint investigation representatives from
Host Community
Department of Petroleum Resources [DPR]: ✓
National Oil Spill Detection and Response Agency [NOSDRA]: ☑
- State Ministry of Environment [SME]: □
Nigeria Police Force [NPF]:□
Shell Petroleum Development Company [SPDC]:

Tick as applicable

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0352/866/64

27. Appendix 1: Overview sketch of the site



THE SHELL PETROLEUM DEVELOPMENT COMPANY	OFNIGERIA LIMITED
JOINT INVESTIGATION REPORT FOR INCIDENT NO:	0352/866/64

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
·		7
-		
 -		
	<u> </u>	
	 	
 _	/	-
	 	
		/
	<u> </u>	
		