



Overview: Part of spill impact on Biseni Remote Manifold at Biseni. Picture was taken during Joint Investigation of 28th August 2013.



Close up: Leak due to gasket failure on Biseni Remote Manifold at Biseni. Picture was taken during Joint Investigation of 28th August 2013.