JOINT INVESTIGATION REPORT FOR INCIDENT NO: 10880 JIV report S/N: (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 1. Spill incident Number: 1088800 2. Type of incident* OLL SPILL 3. Name of Location 20" OTUMARA - ESCRAVOS PIPELINE 4. Name of nearest community ADJUDATBO 5. State: DELTA 6. LGA WARL SOUTH-WEST 7. Type of Production facility/Installation OIL PIPELINE 8. Asset owner/District PIPELINE B. INCIDENT INFORMATION: 9. Details of incident a. Date of incident: 6TH DECEMBER 2013
b. Start date/time of investigation: 19TH DECEMBER 2013 AT 1409HRP
c. Investigation End date: 17TH DEC. 2013 Actual investigation duration, days: 1 DAY d. Description of spill point environment Firmed soil Loose soil Recently excavated area Swampy Under water Exposed pipe surface Well Platform (on Water) Drill Rig e. Description of leak point (tick as applicable); Drilled hole Hack saw cut ☐ Tear (..._____), Complete Rupture ☐Inward dent, Well head tampering Failed Weld-on illegal hot tap valve, Failed Clamp Missing Pipeline/Flowline Crude oil theft (illegal bunkering) point, Third party tampering with Clamp Third party tampering with valve setting, Third party tampering with flange, ☐Corrosion Saver-pit over flow. Surge vessel overflow, Flare System/Bund wall failure Accidental Bulging Outward party equipment impact □Valve Failure Com unit failure Cold vent

f. Incident caused by:

Third party interference (Sabotage ; crude the file; Line the file; Accidental 3rd party damage)

Operational Others (including Mystery spills)

g. Spill point coordinates

Measuring unit MTRL MNNA (WEST BELT)

Northing:

Spill Point 1: 174143 MN 309091 ME

Spill Point 2: 172337 MN 308623 ME

Others (specify)

Relief valve failure

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1088800 JIV report S/N: 0448

Ċ. F	RISK ASSESSM	ENT					
	10. Тур	oe of environment:					
	□ Land	Swamp	□Water	☐ Seaso	onal swamp 🗀 S	horeline/Wat	terfront
	і, Туре	of environment to	which oil has s	spread;			
	□Land	Swamp	□Water	□River	(identify)	·····	
	ii. Weat	ther condition					
	☐Rain 11. Distance from	Sunny on the nearest sensiti	DDry ive habitat	□Wet	□Windy	□Hot	□cool
		ls n/Pond net	esignated protec	eted area	[,m]	NOM THE	E WITH VICINIT
	12. Containment	measures put in pla	ice;				
	□Booms □Others:	Trench	ПDyke		ral depression	□Pit	
	13. Any pictures (or video coverage?			[N]		
	14. Was there any	y disruption to the i	investigation?		[N] [N]	•	
If ye	s give brief descri	ption:					
<u> </u>		NOT	API	PLICA	BLE		
						<u>.</u>	·
	TYPE/NUMBERS	S OF PROPERTI	ES, IF ANY, F	OUND WITH	UN THE AREA	a of sprea	AD OF OIL
S/Ń	Type of Struc	ctures Descrip	ption Size	Numbe	er	Comment	ts
	NONE	hutte	NAR	A C) F /M	PACT	7
<u> </u>					 	- <u> </u>	

16. Crops/Economic Trees

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 108800 JIV report S/N: 0448

g Medium	Matured	Quantity	Comments
15 25	10	50	
	<u> </u>		
/			
/_	/		
	g Medium 15 25	Medium Matured 15 25 10	Medium Matured Quantity 15 25 10 50


17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description		Quant	ity/Size	Comments
	NONE 1	AUTHIN	- ARE	A	0.E	IMPACT

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	MANE	ALITHIN	AREA DE	MPACT
	140:00	7000 [() ()	1	

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)



20" OTUMARA-ESCRAVOS PIPELINE AT ADJUDATBO

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 108800 JIV report S/N: 0448

19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

007	MINNA (W	EPT BELT)
S/N	Northing (M)	Easting (M)
	174008	309060.7
	174014.2	309051.5
	174143.2	209088.3
	174155.5	309 097.5
	174195.4	309106.7
	174192.4	309109-8
	172327.5	308613.5
	172401.3	308644-1
	172 410.5	308628.8
	172315.8	308631.2
	(12013:0	3,0621.7
		
	 ////////	ļ/
	/	
·········		

G. INCIDENT INFORMATION:

20. Impacted Area Details

•	Total calculated area of impact_	2900 m ²
•	Impact within SPDC R.O.W	2 600 m ²
•	Impact outside SPDC R.O.W	300m²

21. Volume of oil recovered before completion of JIV (V_{recJ}):

a. Computatio i. ii. iii.	Recovered oil V _{reci} : on of estimated residual volume on site on of estimated volume of pool of free phase oil (on	MIC	Barrels
a. Computatio i. ii. iii.	n of estimated volume of pool of free phase oil (on		
ii. iii.	Area (m²) occupied by pool of free phase oil	land or confined wa	ter body).
iii.	Average Depth (m) of pool of free phase oil0		
	Emulsification factor: 30 7s		
îv.	Estimated Volume of pool of free phase of V _{pool} :	31.0	4 barrels
	on of estimated volume of infiltrated oil in the soil (mated Volume of infiltrated oil at spill point (Vinf		
i.	Area* (m²) of soil covered by the oil:	4	
ii.	Average Depth (m) above leaking facility i.e. mp	dine/flowline:	·
iii.	Soil type: iv. Pe (effective por	rosity of the soil)	
v.	Cause of spill: yi \ Off type:		
vii.	Oil Residence time on site, da Y		
viii.	Average depth of infiltration below leaking facility	ty i.e. pipeline/flowl	ine:
ix.	Estimated depth of diltration around spill point:		.
	Estimated Volume of infiltrated oil at spill po	oint, V _{iut_a} :	JIL barrel
2. Esti	mated Volume of infiltrated oil at second spill poin	t [if applicable] (Vir	ıf b)
i.	Area* (m²) of soil covered by the oil:		
ii.	Average Depth (m) above leaking facility i.e. pip	elineXHowline:	··
iii.	Soil type: iv. Pe (effective per	fosity of the soil)	· · · · · · · · · · · · · · · · · · ·
v.	Cause of spill: vi. Oit Ope:		
vii.	Oil Residence time on site, day:		
viii.	Average depth of infiltration below leaking facili	ty i.e. pipeline/flowl	ine:
ix.	Estimated depth of infiltration fround spill point:		
	Estimated Volume of infiltrated oil at spill point.	inf b AIL	barrels
3. E		*** *** *** *** ***	or e s
	nated Volume of infiltrated oil outside immediate sp		/int c)
i.	Area (m2) of soil covered by the oil: 55	U M	POLICARIE
ii, 	Area (m²) of the pool of free phase oil in touch w	tin soii: N V I 71	02 %
iii,	Average Depth (m) below ground surface of infil	tration of oil:	- FTS
iv.	Soil type: $\angle ATEATE$ P_e (effective porosity of the soil). 20 7	<u>,</u>	
v,	re tenective potosity of the son).	<u> </u>	

23. Computation of estimated volume of oil on open water based on standard coloration.

i. Total area of oil on open water: MOT APPLICABLE

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1088800 JIV report S/N: 0448

ii. Table of average depth of oil on water based on coloration (

**Spill Factors from USCG FOG (2000 Edition)

·	Thickness (mm)	Percentage coverage	Volume (m3)
Barely Visible	0.00004		4
Silvery	0.00008		
Slight Color	0.00015		X.
Bright Color	0.0003		.0
Dull	0.001	l le	
Dark	0.002	P'	
Black oil	0.1		·
Emulsion (30% Oil)	1	120	

iii. Percent Total 100%

Estimated Volume of oil on open water. V_{wat}: N(L Barrels

24. Calculation of evaporated volume:

- i. Estimated Volume available for evaporation within surface area: 44.88 BBL &
- ii. E-Factor: 15 16

iii. Estimated Volume of evaporated oil. Vevap: 7.92 Barrels

Evap	oration Factors	(E-Factor) for SP	DC Crude oil
Oil Type	Days on site	Bonny Light	Bonny Medium
Oil Residence time	< 1 day	10%	5%
	1-7 days	25%	15%
	> 7 days	40%	25%

25. Net Estimated Spilled Volume
$$V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recl}(bbls) = 7.92 + 13.84 + 31.04 = 52.7988LS$$

Estimated Reported Volume** $V_{rep}(bbls) = 53$ BBLS

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of | I bbl | is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ------ Reported volume = 16 bbl Calculated volume = 0.35 bbl ------ Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ------ Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

26. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out

-	THE SHELL PETROLEUM DEVELOPMENT CON	IPANY OF NIGERIA L	IMTED.
VMI TMOL	ESTIGATION REPORT FOR INCIDENT NO:	JfV report S/N:	0448
В.	Investigation of the incident site showed that there is re works	sidual impact on site req	uiring further
	7. REPRESENTATIVES	A	
This repres	report was filled, agreed and signed on the 7.218 entatives from	12 /20 3 by joint in	vestigation
	Host Community: 52		
•	Department of Petroleum Resources [DPR]:		
٠	National Oil Spill Detection and Response Agency [NOSD	RA]: 🌠	
•	State Ministry of Environment [SME]: 5		
,) (2.	Nigeria Police Force [NPF]:		
	Shell Petroleum Development Company [SPDC]:		
	Signatories agree with reported findings:		
•	Separate DPR form has been filled out with same findings	•	
		Tick as	applicable

28. Appendix 1: Overview sketch of the site

* -		
Location: 20"	OTUMARA - ESCRAUDE	PIPELINE AT ADJUDAIRO

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1088800 JIV report S/N: 0448

OCINT INVESTIGATION (TOTAL) OILT	OR INCIDENT NO: 10000 SUPERING SIN: 0446
	IMPACTED THURD PART PORTEST IMPACTED RIGHT OF WAY
	20" OTUMANA TO ESCRAVOS PIPELIM IMPACTED AREA