JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1092330 JIV report S/N: (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 1092330 2.Type of incident* OIL SPILL 1. Spill incident Number: 16" NUNRIVER - KOLOCREEK PIPELINE 4. Name of nearest community OPOROMA 5. State: BAYELSA 6. LGA SOUTHERN IJAW 7. Type of Production facility/Installation DIL PIPELINE8. Asset owner/District PIPELINE **B. INCIDENT INFORMATION:** 9. Details of incident DECEMBER, 2013 23Rb a. Date of incident: o. Start date/time of investigation: 29TH DECEMBER, 2013/12:37 Hours c. Investigation End date:29TH DECEMBERActual investigation duration, days: 0NE(1)DAY d. Description of spill point environment ☐Firmed soil Recently excavated area Loose soil ☐Under water ☐ Swampy DExposed pipe surface ☐Well Platform (on Water) □Drill Rig e. Description of leak point (tick as applicable); Hack saw cut ☐Drilled hole ☐ Tear (Complete Rupture □Inward dent. ☐Well head tampering □ Failed Weld-on illegal hot tap valve, □ Failed Clamp ☐Missing Pipeline/Flowline Crude oil theft (illegal bunkering) point, ☐ Third party tampering with Clamp ☐ Third party tampering with valve setting, ☐ Third party tampering with flange, ☐ Corrosion ☐Saver-pit over flow, ☐Surge vessel overflow, ☐Bulging Outward □Flare System/Bund wall failure □Accidental party □Valve Failure equipment impact Com unit failure Cold vent

g. Spill point coordinates

| Measuring unit | MINNA (MID BELT) |
| Northing: | Easting: |
| 89535 - 00 mN | 404591-01mE

Others (specify)

Third party interference (Sabotage ; crude theft□; Line theft□; Accidental 3rd party damage□)

Relief valve failure

f. Incident caused by:

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1092330 JIV report S/N: 0370

C.	RISK AS	SESSMENT						
	10.	Type of envi	ronment:					
	12	and \square_{S_1}	wamp 🔲	Water '	Seasonal swamp	Shoreline/Wa	aterfront	,
i. Type of environment to which oil has spread:								
ILand Swamp Water River (identify) ii. Weather condition								
	□R 11. Dista	ain Su ance from the near	•	Dry □W itat	et D Windy	□Hot	□cool	
Government reserved and designated protected area [,m] Drinking water source [,m] Built up area [,m] Farmlands [,m] Fish Farm/Pond [,m] Fishing net [,m] Others (specify). RAFFIA PALM IMPACTED BY SPIL								SPILL.
	12. Cont	ainment measures	put in place;					
		Booms DT:	rench IA PALI		Natural depressio	n 🗖 Pit		
		pictures or video			[XV [1	1]		
	14. Was	there any disrupti	on to the investi	gation?	[Y] [Y	₩		
If :	yes give br	ief description:		1 PP	LIC	AB	LE	
D.	TYPE/N	UMBERS OF PR	OPERTIES, IF	ANY, FOUN	O WITHIN THE A	REA OF SPRE	EAD OF OIL	
	15. Stru	ctures / Propertie	es					
S/I	N Type	of Structures	Description	Size	Number	Comme	nts	

1	_		_
<u> </u>	6. Crops/Economic	Tree	28

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 09 2330 JIV report S/N:

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
1.	RAFFIA				I mT	WITHIN
	PALM					SPILL-
	TREES					IMPACTE
<u> </u>						REGION
				<u> </u>		
<u></u>	<u> </u>	<u></u>				

17. Fish/Nets/Ponds

CALCULATION

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments			
	VONE	WITHIN	AREA	OF IMPAC			
		<u> </u>					

18. Others (Specify) i.e. Animal Traps

S/N Others	Description	Quantity/Size Comments
Marie	Mercu	A 0= 0
HUNE	WITHIN	TIKEA OF IMPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTION OF 16" NUNRIVER - KOLOCREEK PIPELINE AT OPOROMA SHOWING POSITION OF HACKSAW CUT.




TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1092330 JIV report S/N: 0370

19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

MINNA	(MID BELT)
S/N Northing (m)	Easting (m)
WP271 89544.26	404578 71
wP272 89550 · 40	404581.82
WP273 89550.24	404628.07
NP274 89562.40	404665.11
W1275 89562 38	404671.28
WP276 89516 · 54	404597.12
WP277 89516 · 56	404590.95
WP278 89544.29	404572.55
WP279 89578 72	404709.14
WP280 89574·43	404690.09
WP281 89570.14	404716.91
WP282 89534.27	404634.37
WP283 89477.91	404470.86
MP287 89471.16	404497.71
WP285 89494·85	404484.21
W286 89525.27	404547.72
W187 89 433.62	404559-99
MP288 89489.93	404577.14

G. INCIDENT INFORMATION:

20. Impacted Area Details

•	Total calculated area of impact	0.88 Ha	
•	Impact within SPDC R.O.W	YES	
•	Impact outside SPDC R.O.W	YES	


21. Volume of oil recovered before completion of JIV (V_{recI}):

		Recovered oil	V _{rec.j} :	1.51		Barrels
22. Computa	tion of estimated	residual volume on	site			
		lume of pool of free poied by pool of free pl		n land or con		·).
ii	. Average Depth	(m) of pool of free pl	nase oil	0.0	04	
iii	. Emulsification i	factor: NIL				
iv	Estimate	d Volume of pool of	free phase o	oil."		barrels
		V _{pool} :		<u> </u>	18.06	
		lume of infiltrated oil infiltrated oil at spill				
i.	Area* (m²) of so	oil covered by the oil:		1		
ii.	` •	(m) above leaking fac		eline/flowlin	e: 1.4 A	^
iii.	Soil type: S1	· <u>-</u> -		rosity of the		<u>;</u>
v.	Cause of spill:	HIRD VI.	Oil type:_	BON		HT
vii.	Oil Residence ti	TEKFERENCH	6 DA	•	 , · - ·	•••
viii.		of infiltration below le			ne/flowline: 0	·lm
ix.		of infiltration around			m	
2. Es	。2010年前清洁整整590000	Volume of infiltrated of		erre un grandation	le] (Vinf b)	barrels
í,	_	oil covered by the oil:	• •			. 01
ii.		n) abyve leaking fac	ility i.e. pir	eline/flowlin	e: \ [JKI
iii.	Soil type:	1 1 1		rosity of the	— *****	106
٧.	Cause of spill:		Oil type:	V)	/ `	 -
vîi.	Oil Residence ti	me n site, day:		$\mathcal{I} V$	₹	
viii.	1	f infiltration below le	aking facili	ty e. pipelin	e/flowline:_	
ix.	Estimated depth	of infiltration around	spill poin			
3. E	Talupalus Voluin	e of infiltrated oil at s	Pill politis?	24	NIL B	arrels
	nated Volume of in	ıfiltrated oil outside ir	nmediate s	pill point(s) re	egion (Vinf c)	
i.		il covered by the oil:	~~ •q	q	8	
ii.		pool of free phase oil	in touch w	rith soil:	NIL	
iii.		(m) below ground sur			• • • •	
iv.	Soil type:	· ·				_
v.		rosity of the soil).	21°/	, O		
·		nated Volume of infilt	rated oil. A	t V _{inf}	12.94	barrel
	-	volume of oil on ope				

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 092330 JIV report S/N: 0370

ii. Table of average depth of oil on water based on coloration (

**Spill Factors from USCG FOG (2000 Edition)



Percent Total 100%
iii. Estimated Volume of oil on open water. V_{wat}: Barrels

24. Calculation of evaporated volume:

i. Estimated Volume available for evaporation within surface area: 234.5 BARRELS

ii. E-Factor: 25%

iii. EstimatedVolume of evaporated oil. V_{evap}:

8-17 Barrels

Evaporation Factors (E-Factor) for SPDC Crude oil							
Oil Type Days on site Bonny Light Bonny Medium							
Oil Residence time	< 1 day	10%	5%				
-	1-7 days	25%	15%				
> 7 days 40% 25%							

25. Net Estimated Spilled Volume
$$V_{Exp}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{psol}(bbls) + V_{recl}(bbls) = 78 \cdot 17 + N1L + 14 \cdot 93 + 218 \cdot 06 + 1.51 = 312 \cdot 66$$

Estimated Reported Volume** $V_{reg}(bbls) = 313$ BARRELS.

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of I bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

26. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1092330 JIV report S/N: 0370

B. Investigation of the incident site showed that there is residual impact on site requiring further works

27. REPRESENTATIVES

This report was filled, agreed and signed on the 29/10 /2013 by joint investigation representatives from

- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]: 5
- State Ministry of Environment [SME]: IN
- Nigeria Police Force [NPF]:
- Shell Petroleum Development Company [SPDC]: 5
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings

Tick as applicable

28. Appendix 1: Overview sketch of the site

Location: 16"	NUNRIVER -	KOLOCREEK	PIPELINE	AT OPOROMA
;				
		_		•

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 109 2330 JIV report S/N: 0370

