THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA HITTED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 98685 JIV report S/N:

(Note: As practicable as possible the JIT report is to b	e signed in the field by all the participating parties)
A. GENERAL INFORMATION:	
1. Spill incident Number: 986685	2.Type of incident* OIL SPILL
3. Name of Location 10" DIEBU CREE	K-NUM RIVER PIPELINE
4. Name of nearest community ONTOMALE	5. State: BAYHESA. LGA SOUTHEAN IJAI
7. Type of Production facility/Installation OIL DI	PELINE 8. Asset owner/District PIPE-LINE EAST
B. INCIDENT INFORMATION:	
9. Details of incident a. Date of incident: 3RD Juni F, 2013 b. Start date/time of investigation: 22MB Juni F, 2013 c. Investigation End date: 22MB Juni F, 2013 d. Description of spill point environment	3 M+, 20/3 / 10:446AM Actual investigation duration, days: <u>OME(1) DN-1</u>
☐Firmed soil ☐Loose	soil Recently excavated area
☐Under water ☑Swam	py DExposed pipe surface
☐Well Platform (on Water)	□Drill Rig
e. Description of leak point (tick as applicable)	
Drilled hole	
Complete Rupture	<u> </u>
☐ Failed Weld-on illegal hot tap valve, ☐ Faile	
Crude oil theft (illegal bunkering) point,	☐ Third party tampering with Clamp
☐ Third party tampering with valve setting,	☐ Third party tampering with flange,
-	-pit over flow, Surge vessel overflow,
☐Bulging Outward ☐Flare	System/Bund wall failure Accidental 3rd party equipment
impact	□com unit failure □Cold vent :
Relief valve failure Other	s (specify)
f. Incident caused by: Third party interference (Sabotage 2, crude of the conding of the coordinate) g. Spill point coordinates Measuring unit Northing: SP 85289-30m	na — Mid bett · Easting:

NT INVE	ESTIGATION I	REPORT FOR IN	CIDENT NO:_	9868	685 J	IV report	t S/N:	0114
	SK ASSESSM					-		0114
	10. Тур	e of environment:			÷			
	☑ Land	wamp	□Water	√ZSe	asonal swar	np□Sho	reline/Wa	aterfront
	i. Type	of environment to	which oil has sp	oread:				
	L Land	DSwamp	□Water	□Ŕi	ver (identify	y) <u> </u>		
	ii. Wea	ther condition						
11	☐Rain . Distance from	Sunny the nearest sensiti		□Wet	□wind	ly	□Hot	□cool
	Governm Drinking Built up Farmland Fish Farn Grishing I		esignated protection	ed area	[[[[,m] ,m] ,m] ,m] ,m] ,m]		
12	2. Containment	measures put in pla	nce;					
	☑Booms □Others:_	Trench	□Dyke.	□na	atural depre	ssion	Ø Pit	
13	3. Any pictures	or video coverage?	•		W	[N]		
14	4. Was there an	y disruption to the	investigation?		[Y]	M		
If yes	give brief descr	iption:						
	MOT	APP	LICA	BL	E			
D. TY	YPE/NUMBER	S OF PROPERTI	ES, IF ANY, F	DUND WI	THIN THI	EAREA	OF SPRI	EAD OF OIL
1:	5. Structures /	Properties						
	Type of Stru	ctures Descr	ription Size	N	umber_		Com	ments
S/N			ı					
S/N								10.0

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 986685 JIV report S/N:

		<u> </u>	 	
Crops/Economic Trees	į			

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	-					
┢	00/6-	11/1/14/11/	1_0	C- A	OF The	nas
14	10/1/ t	WH HIM	17 K	- TK	47 <u>J</u>	
						<u> '</u>
			<u> </u>	<u> </u>		

17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
A	ONE	WITHIN	AREA	OF IMPACT

18. Others (Specify) i.e. Animal Traps


S/N Others	Description	Quantity/Size	Comments
None	WITHIN AF	CA OF	IMPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

leak report, overview sketch of the site should be added as an appendix 1)

SECTION OF 10" DIEBU CREEK - NUN RIVER PIPELINE AT ONYOMAL

SHOWAN & POCITION OF HACK SAW CW AT 1 0" CLOCK POSITION.



FROM DIEBU CREEK TO NUMBIYER

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 986885 JIV report S/N: 0114

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 19. Impacted area boundary Coordinates (If more, Print and attach is an appendix)

		IIINNA	- Maber.
	S/N		Easting (M)
1	W418	85277.04	404859.77
į	P419	85261·68 85255·54 85240·19	404 856 63
'n	P420	85255.54	404 856.61
·	P421	85240.19	464 850 · 39
h	P422	85240·20	404847.31
h	P424	R5264.73	404 8 62 81
K	Rua Ti	200tt-49	404 868 94
h	426	85249.33	404 875.09
h	W427	85264.70	404 8 62. 81 404 868.94 404 875.09 404 872.06
V	P429	85267.78	1404 877 . 07
٨	P430	85276.96	404 884.44
4	P431	85276·96 85267·68	404 884·44 404 899·82 404 887·59
ì	M432	85298 . 46	404 887 .59
Ì	of 433	85298 · 46 85313 · 84 85316 · 98 85310 · 86 85304 · 70 - 85298 · 55	A04 884.56
V	M434	85316.98	404 866.07
1	P435	85310.86	404 856.80
į	P436	85 304.70	404 859 86
	M437	- 85 298 ·5 5	404 862.93
	MYYST	1 2 1 20 5 : 1 2	404 865 96
١	W 439	85261.501	404 909 . 05
1	N 439 M 440	8526 .501 85249 - 28 85230 .78 85203 - 15 85178 . 58	404 909 · 05 404 905 · 92 404 905 · 86
l	MUY	85230.78	404 905. 86
1	W442	65203-15	404 896.51
	MUY	85178.58	404 890.26

See attached

PTS	NORTH	EAST
WP444	85169.303	404905.645
WP445	85175.322	404942.668
WP446	85175.429	404911.833
WP447	85175.504	404890.249
WP448	85166.294	404887.133
WP449	85166.348	404871.716
WP451	85166.423	404850.131
WP452	85172.581	404847.069
WP453	85175.676	404840.913
WP454	85191.055	404837.883
WP455	85206.412	404841.02
WP456	85218.707	404841.063
WP457	85240.222	404841.138

22/06/2013

UI14
JOINT INVESTIGATION REPORT FOR INCIDENT NO: 986685 JIV report S/N:
G. INCIDENT INFORMATION:
20. Impacted Area Details
• Total calculated area of impact 0.778587kg (0.78kg)
Impact within SPDC R.O.W
Impact outside SPDC R.O.W
21. Volume of oil recovered before completion of JIV (V _{recl}):
Recovered oil V _{recJ} : 20.44 Barrels
 22. Computation of estimated residual volume on site a. Computation of estimated volume of pool of free phase oil (on land or confined water body). i. Area (m²) occupied by pool of free phase oil
ii. Average Depth (m) of pool of free phase oil
Estimated Volume of pool of free phase oil. V _{pool} : 21.59 barrels
 b. Computation of estimated volume of infiltrated oil in the soil (V_{inf}). 1. Estimated Volume of infiltrated oil at spill point (Vinf a)
i. Area* (m²) of soil covered by the oil:
ii. Average Depth (m) above leaking facility i.e. pipeline/flowline: $\frac{1 \cdot S}{V}$ iii. Soil type: $\frac{CLAV}{V}$ iy. P_c (effective porosity of the soil).
iii. Soil type: CLAY iv. Pc (effective porosity of the soil). 8% THURS PARTY v. Cause of spill Suffer Fly and the soil of type: BONAY LIGHT
vii. Oil Residence time on site, day: 19 DAYS
viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline: 0.0052 M
ix. Estimated depth of infiltration around spill point: 1.5052 M
x
Estimated Volume of infiltrated oil at spill point. V _{inf_a} : 3.03 barrels
2. Estimated Volume of infiltrated oil at second spill point [if applicable] (Vinf b)
i. Area* (m²) of soil covered by the oil:
ii. Average Depth (m) above leaking facility het sipeline/flowline:
iii. Soil type: iv_ Reference porosity of the soil)
v. Cause of spilk: VI. Oil type:
vii. Oil Resilience time on site, day:
viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline:
ix. Estimated depth of infiltration around spill point:
Estimated Volume of infiltrated oil at spill point. V _{inf_b} : barrels

3. Estimated Volume of infiltrated oil outside immediate spill point(s) region (Vinf c)

NT INVESTIGATION F	EPORT FOR I	NCIDENT NO: 98	36685	.IIV report S/N:	กา 1 4
		covered by the oil:	6,08	<u> </u>	
ii. A	rea (m²) of the n	ool of free phase oil	in touch with s	oil: 1,7/6	
	•	i) below ground surfa		, _	052
	oil type:		acc or minimalit	on or on	
			8%		
v. ,	•	sity of the soil)			
v	i. Estima	ted Volume of infiltr	ated oil. At V _{it}	af: 20.	42 barrels
00	-62	.1	414		4:
-			n water based	on standard colora	mon.
	of oil on open wa	il on water based on	coloration (_	
n. <u>rabie or av</u>	rerage depair or o	II OII WAICI DASCU OII	Coloradion	**Spill Factors from Edition)	USCG FOG (2000
	Thickness	Percentage			
	(mm)	coverage	Volume (m3)	1	
Barely Visible				-	
Silvery	0.00008			<u> </u>	
Slight Color	0.00015	/ 2 - -		-	
Bright Color	0.0003 / 4	000	ple	-	
Dull	0.001	PALCOL	<u> </u>	-	
Dark	0.002	•	_	_	
Black oil	0.1				
Emulsion (30% Oil)	1]	
	Percent Total	100%			
iii.	Estimated Volu	me of oil on open w	ater. V _{wat} :	MIL	Barrels
24. Calculation of	of evaporated vo	olume:			
	mated Volume a actor: <u>40 %</u>		ration within s	surface area: 69	<u>5-44</u> Barr
iii.	EstimatedV	olume of evaporated	oil. V _{evap} :	43.65	Barrels
Evan	oration Factors	(E-Factor) for SPI	OC Crude oil		
Oil Type	Days on site	Bonny Light	Bonny Med	dium	
Oil Residence time	< 1 day	10%		5%	
	1-7 days	25%		15%	
	> 7 days	40% レ		25%	
(bbls) + V _{rec}	; (bbls) = 43 = 109	13 BARRE	23.45	- V _{wat} (bbls) + V _{int} - 入1·59 - 110 BARRE	20.44
Estimated Reported	<u>Volume** V_{ren}(t</u>	obls)≡ }∫U	BARRE	15.	
		110	WAKE C	<u> </u>	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 986655 JIV report S/N: 0114

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than I bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ------ Reported volume = 16 bbl

Calculated volume = 0.35 bbl ------ Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ------ Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

26. GENERAL STATUS OF THE SITE

- A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out
 - B. Investigation of the incident site showed that there is residual impact on site requiring further works

27. REPRESENTATIVES

This report was filled, agreed and signed on the $\frac{12}{\sqrt{6}}$ /20/3 by joint investigation representatives from

- Host Community:
- Department of Petroleum Resources [DPR]: □
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]: 🗹
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings□

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 986685 JIV report S/N: 0114

28. Appendix 1: Overview sketch of the site

