THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED.
JOINT INVESTIGATION REPORT FOR INCIDENT NO: 987213 JIV report S/N:
(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)
A. GENERAL INFORMATION:
1. Spill incident Number: 987213 2. Type of incident* OIL SPILL
3. Name of Location 14" OKORDIA - RUMUEKPE PIPELINE
4. Name of nearest community IKARAMA 5. State: BAYEL SA 6. LGA YENAGOA
7. Type of Production facility/Installation OIL PIPELINE 8. Asset owner/District PIPELINE
B. INCIDENT INFORMATION:
a. Date of incident: 4 Th TUNE, 2013. b. Start date/time of investigation: TH JUNE, 2013 2:48 Hours c. Investigation End date: TH JUNE, 2013 Actual investigation duration, days: TWO(2) DAYS d. Description of spill point environment Firmed soil
Relief valve failure Others (specify)
f. Incident caused by: ☐ Third party interference (Sabotage☐; crude theft☐; Line theft☐; Accidental 3 rd party damage☐) ☐ Operational ☐ Others (including Mystery spills)
g. Spill point coordinates Measuring unit Northing: (m) Easting: (m)
Northing: (m) Easting: (m)
127782.45 443694.19

IOINT INVESTIGATION F	REPORT FOR IN	CIDENT NO:	9872	JIV rep	ort S/N:	188
C. RISK ASSESSM	ENT				U	, 00
10. Тур	e of environment:			7		
□Land	☐Swamp	□Water	⊿ Se	asonal swamp DS	horeline/Wate	afront
i. Type	of environment to	which oil has	spread:			
□Land	Swamp	HL □Water	□Ri	ver (identify)		
ii. Weat	ther condition					
Rain 11. Distance from	Sunny the nearest sensiti	□Dry ve habitat	□wet	□Windy	Hot	□cool
☐ Drinking☐ Built up a☐ Farmland☐ Fish Farm☐ Fishing n☐ Others (s	area s n/Pond et pecify). TALM	TREES	ected area	[,m] [,m] [,m] [,m] [,m]	М АСТЕ) В	Y SPILL.
12. Containment	_	_	_		_	
☐Booms ☐Others:	□Trench	□Dyke	↓ ZNa	ntural depression	□Pit	
13. Any pictures	or video coverage?			[X] [N]		
14. Was there any	disruption to the i	nvestigation?		[Y] [N]	/	
If yes give brief descri	ption:					
	T	AP	PL	1CA	BL	
D. TYPE/NUMBERS	OF PROPERTI	ES, IF ANY, I	OUND WI	THIN THE AREA	A OF SPREA	D OF OIL
15. Structures /]						
S/N Type of Struc	-	iption Size	No	ımber	Comme	nte
Wit Type of Bilde	vares Descr	DHOH DIZE	140	STRAIFUL	Comme	AB.,7
			1			
MALE	\1/1-		Δc	FAA	EIN	TOAD

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 987213 JIV report S/N:

16. Crops/Economic Trees	 S		

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
1	PALM RES				5	MITHIN
├─ ₹•	FATLINI DEED					SPILL-
 						IMPACTED
-				-		REGION.
				<u> </u>		

17. Fish/Nets/Ponds


S/N Fish/Nets/Ponds	Description	Quantity/Size	Comments	
NONE	WITHIN	AREA O	FIMPACT	

18. Others (Specify) i.e. Animal Traps

S/N Others	Description	Quantity/Size	Comments
NONE	WITHIN A	REA	OF IMPACT


E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTION OF 14" OKORDIA - RUMUEKPE PIPELINE AT IKARAMA SHOWING POSITION OF HACKSAW CUT.



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 987213 JIV report S/N: 0088

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)



14" OKORD	IA TO RUMUEKPE TRUNKL	INE AT IKARAMA
	APPENDIX A	
	IMPACTED AREA COORDIN	IATES
	INCIDENT NO:987213	S
	MINNA_MID	BELT
POINT	NORTHING(m)	EASTING(m)
135	127788.64	443681.88
136	127776.34	443681.84
137	127770.19	443684.91
138	12 7764.0 7	443675.64
139	127764.08	443672.56
140	127764.11	443663.32
141	127788.64	443681.88
142	127767.22	443651.01
143	127770.31	443647.93
144	127776.43	443654.12
145	127779.51	443654.13
146	127770.32	443644.85
147	127779.56	443638.72
148	127782.63	443638.73
149	127788.77	443638.75
150	127794.92	443638.77
151	127797.97	443644.94
152	127804.15	443635.72
153	127782.66	443629.49
154	127782.69	443620.25
155	127765.22	443653.31
156	127761.07	443654.07
157	127761.08	443650.99
158	127761.09	443647.9
159	127767.23	443647.92
160	127758.05	443638.65
161	127758.06	443635.57
162	127767.25	443633.37
163	127748.76	443641.76
164		443660.19
	127745.68	443647.84
165	127739.58	443623.14
166	127724.29	<u> </u>
167	127782.45	443694.19
168	127791.71	443681.89
169	127800.88	443697.33
170	127791.66	443697.3
171	127791.62	443709.62
172	127788.54	443712.69
174	127785.46	443712.68
175	127779.32	443712.66
176	127779.31	443715.75
177	127782.37	443718.84
178	127782.34	443728.08
179	127785.4	443731.17

180	127785.38	443737.33
181	127782.29	443743.48
182	127782.28	443746.56
183	127773.07	443743.45
184	127742.34	443743.36
185	127739.26	443746.43
186	127730.03	443749.48
187	127726.95	443752.55
188	127720.81	443749.45
189	127720.83	443743.29
190	127711.66	443727.85
191	127699.4	443718.57
192	127696.35	443712.4
193	127696.36	443709.32
194	127693.32	443700.06
195	127684.16	443681.55
196	127684.18	443675.39
POND		
198	127705.56	443715.51
199	127711.7	443715.53

NT INVESTIGATION REPORT FOR INCIDENT NO: 987213 JIV report S/N:	8800
G. INCIDENT INFORMATION:	
20. Impacted Area Details	
Total calculated area of impact_0.98Ha	
Impact within SPDC R.O.W	
Impact outside SPDC R.O.W CS CS CS CS CS CS CS C	_
21. Volume of oil recovered before completion of JIV (V _{recl}):	
Recovered oil V _{recj} :	Barrels
22. Computation of estimated residual volume on site	
a. Computation of estimated volume of pool of free phase oil (on land or confined water book i. Area (m²) occupied by pool of free phase oil	iy).
ii. Average Depth (m) of pool of free phase oil	
iii. Emulsification factor:	•
iv F	barrels
Estimated Volume of pool of free phase oil. V _{pool} : 369.	
b. Computation of estimated volume of infiltrated oil in the soil (V _{inf}).	
Estimated Volume of infiltrated oil at spill point (Vinf a)	
i. Area* (m²) of soil covered by the oil:	
ii. Average Depth (m) above leaking facility i.e. pipeline/flowline:	
iii. Soil type: CLAY iv. P_e (effective porosity of the soil). 86 v. Cause of spill: INTERFERENCE vi. Oil type: BONNY MED W	
	(M
vii. Oil Residence time on site, day: 4 DAYS	a. nolaa
viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline:	7.001M
	_
Estimated Volume of infiltrated oil at spill point. Vinf. a:	78 barrels
2. Estimated Volume of infiltrated oil at second spill point [if applicable] (Vinf b)	
i. Area* (m²) of soil covered by the oil:	OIE
ii. Average Depth (m) above leaking facility i.e. pipeline/flowline:	RLL
iii. Soil type: V. Pe (effective porosity of the soil)	<u>, </u>
v. Cause of spill: Vi. Oil type:	
vii. Oil Residence time of sile, day:	
viii. Average depth or infinite tion below leaking facility i.e. pipeline/flowline:	
ix. Estimated depth of infiltration around spill point:	
Estimated Volume of infiltrated oil at spill point. Vinf. b:	barrels
•	

3. Estimated Volume of infiltrated oil outside immediate spill point(s) region (Vinf c)

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED. JOINT INVESTIGATION REPORT FOR INCIDENT NO: 987213 JIV report S/N: NIL Area (m2) of soil covered by the oil: _____ i. Area (m²) of the pool of free phase oil in touch with soil:___ 00 ii. Average Depth (m) below ground surface of infiltration of oil:___ üì. Soil type: ___CLAY iv. P_e (effective porosity of the soil)._ ٧. barrels Estimated Volume of infiltrated oil. At Vinf. **b**-06 23. Computation of estimated volume of oil on open water based on standard coloration. Total area of oil on open water:___ NIL Table of average depth of oil on water based on coloration (**Spill Factors from USCG FOG (2000

	Thickness (mm)	Percentage coverage	Volume (m3)
Barely Visible	0.00004		
Silvery	0.00008	11-	-
Slight Color	0.00015	IVO	<u> </u>
Bright Color	0.0003		
Dull	0.001	,	
Dark	0.002	Appi	CABLE
Black oil	0.1	1111 L	CHOLL
Emulsion (30% Oil)	1		

iii. Percent Total 100%

Estimated Volume of oil on open water. V_{wat}: Barrels

- 24. Calculation of evaporated volume:
 - i. Estimated Volume available for evaporation within surface area: 379-93 BARRELS

Edition)

ii. E-Factor: 5%

iii. Estimated Volume of evaporated oil. V_{evap}: 67.05 Barrels

Evaporation Factors (E-Factor) for SPDC Crude oil				
Oil Type	Days on site	Bonny Light	Bonny Medium	
Oil Residence time	< 1 day	10%	5%	
	1-7 days	25%	15%	
	> 7 days	40%	25%	

25. Net Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recl}(bbls) = 67.05 + NL+ 0.84+ 369.1 + 10 = 446.98$ Estimated Reported Volume** $V_{rep}(bbls) = 447$ BARRELS,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 987213 JIV report S/N: 0088

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than I bbl is rounded up to the next 0.1 bbl.

Examples:

Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl

Calculated volume ≈ 0.35 bbl ------ Reported volume ≈ 0.4 bbl Calculated volume = 0.01 bbl ------ Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

26. GENERAL STATUS OF THE SITE

- A. Joint investigation of the incident site forms that there is no residual impact after the initial response and therefore recommend that the site be closed out.
- B. Investigation of the incident site showed that there is residual impact on site requiring further works

27. REPRESENTATIVES

This report was filled, agreed and signed on the <u>Q8/66</u>/2013 by joint investigation representatives from

- Host Community:
- Department of Petroleum Resources [DPR]: □
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]: 🗖
- Shell Petroleum Development Company [SPDC]: 5
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 987213 JIV report S/N: 0088

28. Appendix 1: Overview sketch of the site

