



6/25/2014 12:29:16 PM (+1.0 hrs) Lat=5.44418 Lon=5.24512 Alt=26ft MSL WGS 84

Overview: Part of spill impact on Yokri Well 110T Flowline Right of Way at Yokri. Picture was taken during Joint Investigation of 25<sup>th</sup> June 2014.



6/25/2014 1:41:20 PM (+1.0 hrs) Lat=5.44423 Lon=5.24512 Alt=26ft MSL WGS 84

Close-up: Spill due to corrosion on Yokri Well 110T Flowline at Yokri. Picture was taken during Joint Investigation of 25<sup>th</sup> June 2014.