JOINT INVESTIGATION	N REPORT FOR INC	IDENT NO: 1134	ナユロ JIV repo	ort S/N: 0417
(Note: As practicable	e as possible the JIT re	eport is to be signed in t	the field by all the par	rticipating parties)
A. GENERAL INF	ORMATION:			
1. Spill incident Nun	nber: <u>11343</u>	2.Ty	pe of incident*	Hr >hr
3. Name of Location	24" NKPEK	cu - Bomu	TRANS NI	GER PIPELINE
4. Name of nearest c	ommunity <u>BIA</u>	RA 5. State: R		GOKANA.
7. Type of Productio	n facility/Installation _	OIL PIPELINE	8. Asset owner/Distric	ct PIPELINE LAND
B. INCIDENT INFO				Ţ
b. Start date/ti c. Investigatio	me of investigation: for End date: 11 mg. of spill point environm	MCH, 2014Actual in	4. nvestigation duration, Recently exc	
e. Description Drilled h Complet Failed We	tform (on Water) of leak point (tick as a nole te Rupture eld-on illegal hot tap valv il theft (illegal bunkering try tampering with valv on Outward	Hack saw cut Inward dent, re, Failed Clamp ng) point,	☐ Third party to w, ☐ Surge vessel), mpering eline/Flowline ampering with Clamp ampering with flange, overflow, eidental 3 rd party
☐Relief va	ilve failure	Others (specify)		
Operational	interference (Sabotagel	rude theft□; Line t		^d party damage□)
	uring unit M	(MUNNA	MID-BEIT	(1)
SP:	76 339 .	57	Easting: 535	081.53

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

					COMPANY OF NIGI	
JOINT INVE	STIGATION RE	PORT F	OR INCIDENT	гио: <u>113</u>	4211 JIV report	1 S/N: 041 /
	K ASSESSMEI					
1	0. Type	of environ	ment:			
	Land	☐Swar	mp 🗆 W	ater [Seasonal swamp□Sho	reline/Waterfront
	i. Type o	f environr	nent to which o	oil has spread:		
	Land	□Swar	mp 🗖 W	/ater [River (identify)	<u> </u>
	ii. Weath	er conditio	on			
11.	☐Rain Distance from t	Sunn he nearest		-	t	□Hot □cool
	☐ Drinking w ☐ Built up an ☐ Farmlands ☐ Fish Farm/	vater source ea 'Pond'	l and designate e		a [NIL ,m] [NIL ,m] [NIL ,m] [\0 ,m] [NIL,m]	
12	. Containment m	neasures p	it in place;			
	□Booms □Others:	□Tre	nch 🗹	Dyke	Natural depression	⊠ Pit
13	3. Any pictures o	r video co	verage?		[N] \{N]	
14	1. Was there any	disruption	to the investig	ation?	[Y] [N]	
If yes a	give brief descrip	tion:				
=	No	7		PPL	-1 CA	SLE
	YPE/NUMBERS 5. Structures / I			ANY, FOUNI	O WITHIN THE AREA	OF SPREAD OF OIL
S/N	Type of Struc		Description	Size	Number	Comments
3/13						

S/N Type of Structures	Description	Size	Number	Comments
NAIC L	1711	N (*	APCA	- IXI'DACI
11/01/1E X	HH	14	1/1-11	
	 -	 		
	+	t^-		

16. Crops/Economic Trees

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 113421 JIV report S/N: 0417

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
\ <u> \</u>	CASSAYA				Tew	CROP FOUND
<u></u>	14m				FEN	MITHIN AND
						DUTSIDE
<u> </u>					_	STOCKLIGHT
						OF WAY
			+		+	

17. Fish/Nets/Ponds

S/N Fish/Nets/Ponds	S Description	Quantity/Size	Comments	
NONC	XII THE CH	AREA	OF	IMPACT

18. Others (Specify) i.e. Animal Traps

S/N Others	Description	Quantity/Size	Comments
NONE 1	HITHIN AR	CA OF	IMPACT.

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTIONAL VIEW OF 24" NKPOKU - BOMY TRANS MIGHT PIPELIN AT BIARA SHEWING: ILLEGAL HACKSAW CUT.

LEAR IS DUE TO
125mm/emant of HACKSAW

CUT WITH Effective CUT OF

60mm AT 90 CLOCK POSITION.

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1134211 JIV report S/N: 0417

19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

	ally annial	-BetT)
S/N	Northing (M)	Easting (m)
WP962		535 087 71
W1963	76 348 77	535 087. 70
MP964	76 330 35	535 084. 58
WP965	76 333.43	635 081.51
W966	76 336. 50	535 078. 43
N967	76 339.58	535 078 . 44
WP968	<u>76 358 00</u>	535 081.55
W969	76 376.47	535 056.93
W 970	<u> </u>	535 044. 62
M971		535 032, 32
W972	76 419.55	535,013.86
NP973	76 450.34	535 970.77
W974	76 459. 58	534961.54
WP976	76 422. 63	535 010.78
w977	76409.47	535 027.85
M978	76394. 93	535 041.55
W979	76 373.39	535 063.09
W980	76 364.14	535081.56
_		

G. INCIDENT INFORMATION:

20. Impacted Area Details

•	Total calculated area of impact	<u>0.</u> 04 Ha.
•	Impact within SPDC R.O.W	YES
•	Impact outside SPDC R.O.W	YES

21. Volume of oil recovered before completion of JIV (V_{recl}) :

	Recovered oil V _{reel} :	2.	Barrels
22 Computat	ion of estimated residual volume on site		
a. Computati	on of estimated volume of pool of free phase oil (on		body).
ii	Average Depth (m) of need of free phase oil	6.010m	
iii			·
iv		15	barrels
	Estimated volume of pool of free phase of	" ૄ .બજ	Darreis
	V _{pool} :	,	
	on of estimated volume of infiltrated oil in the soil (timated Volume of infiltrated oil at spill point (Vinf a		
i.	Area* (m²) of soil covered by the oil:	2 _{m²}	
ii.	Average Depth (m) above leaking facility i.e. pipe	eline/flowline:	<u>n</u>
iii.	Soil type: SuT iv. Pe (effective por	osity of the soil)	21%
v.	Cause of spill: THEED PARTY vi. Oil type:	BANY MEDIUM	
vii.	Oil Residence time on site, day: Six Dans		
viii.	Average depth of infiltration below leaking facilit	y i.e. pipeline/flowline:	0.006m
ix.	Estimated depth of infiltration around spill point:	1-106m.	
	Estimated Volume of infiltrated oil at spill po	mt. Viii. 2.9	2. barre
2. Est	timated Volume of infiltrated oil at second spill point	[if applicable] (Vinf b)	ı
i.	Area* (m²) of soil covered by the oil:	u.	
ii.	Average Depth (m) above leaking facility i.e. pipe		
iii.	Soil type: SulT iv. Pe (effective por		-
v.	Cause of spill: NIL vi. Oil type: 8		
vii.	Oil Residence time on site, day: NIL		
viii.	Average depth of infiltration below leaking facilit	y i.e. pipeline/flowline:	MIL
ix.	Estimated depth of infiltration around spill point:	MIL	
	Estimated Volume of infiltrated oil at spill point. V		barrels
3. E			
stin	nated Volume of infiltrated oil outside immediate sp	ill point(s) region (Vinf	(c)
i.	Area (m2) of soil covered by the oil:	385m2	
ii.	Area (m²) of the pool of free phase oil in touch wi	th soil:	
iii.	Average Depth (m) below ground surface of infilt		706m
iv.	Soil type: SijT	<u>-</u>	
v.	P_{ϵ} (effective porosity of the soil). 21 %		
·	vi. Estimated Volume of infiltrated oil. At	V. 1.8	baп
	A SECULATION OF SECURATION OF	<u>.74 ∪ 🏲 🖁</u>	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1134211 JIV report S/N: 0/117

ii. Table of average depth of oil on water based on coloration (

**Spill Factors from USCG FOG (2000 Edition)

	Thickness (mm)	Percentage coverage	Volume (m3)
Barely Visible	0.00004		
Silvery	0.00008	NexI	CACN
Slight Color	0.00015	140141	2 CC1
Bright Color	0.0003	L 1,	
Dull	0.001	MIH	M —
Dark	0.002	1	
Black oil	0.1	NO. H	1
Emulsion (30% Oil)	1		

Estimated Volume of oil on open water. Vwat: NOT APPLICABLE Barrels

24. Calculation of evaporated volume:

iii.

- i. Estimated Volume available for evaporation within surface area: 6.75 Braces
- ii. E-Factor: 15 %

iii. EstimatedVolume of evaporated oil. V_{evap}: [. [] Barrels

Evap	отation Factors	(E-Factor) for SP	DC Crude oil
Oil Type	Days on site	Bonny Light	Bonny Medium
Oil Residence time	< 1 day	10%	5%
	1-7 days	25%	15%
<u></u>	> 7 days	40%	25%

25. Net Estimated Spilled Volume
$$V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{tot}(bbls) + V_{pool}(bbls) + V_{rec}(bbls) + V_{rec}(bb$$

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ------ Reported volume = 16 bbl Calculated volume = 0.35 bbl ------ Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ------ Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

26. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out

	Investig works	gation	of the ix	ident site	showe	d that there	is residual in	npact on site requir	ing furthe
27.	REPR	ESEN	TATIVI	es			-		
This r	eport v	vas fil from	led, agr	eed and	signed	on the _	11/03/20	4 by joint inve	stigation
•	Host C	ommu	nity: 🗖						
•	Depart	ment o	f Petrole	ım Resou	rces {Dl	PR : 🗖			
•	Nation	al Oil S	pill Dete	ction and	Respon	se Agency [N	iosdra]: Б∕		
•	State N	linistry	of Envir	onment [S	SME]: E	3/			ĺ
•	Nigeria	Police	Force [N	PF]: 🔂					
•	Sbell P	etroleu	m Develo	pment Co	mpany	[SPDC]: S			
•	Signato	ries ag	ree with r	eported fin	dings: [S			
•	Separa	te DPR	form has	been filled	out with	h same findin	gs 🗖		
							•	Tick as ap	plicable
				w sketch				0.00	
tion :	14.	ukt	<u>ъкц</u>	- 6c	rm4	IRANS	NIGER	PIPELINE	41 2
							-		

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1134211 JIV report S/N: 0417

