JOINT INVESTIG	GATION REPORT FOR INCI	DENT NO: 1135	249 JIV report S/N:	0427				
(Note: As pra	acticable as possible the JIT rep	oort is to be signed in t	he field by all the participating	parties)				
A. GENERA	AL INFORMATION:							
1. Spill incide	ent Number: 113534	2.Tyl	pe of incident* OIL SF	<u>ILL</u>				
3. Name of L	ocation 24" NKPOK	u - Bomu	TRANS NIGER P	ifeli ne.				
4. Name of no	earest community Bine	5. State: 6	INERS 6. LGA GOK	ANA				
	roduction facility/Installation							
B. INCIDEN	T INFORMATION:			·				
b. Start c. Inve d. Desc	incident e of incident: 5 TH MARCH t date/time of investigation: 6 estigation End date: 10 MARCH cription of spill point environm	2514 MARCH, 2514 CH, 2514 Actual in	vestigation duration, days: <u>F</u>					
e. Desc Or Or Or Or Or	Juder water Well Platform (on Water) cription of leak point (tick as appriled hole Complete Rupture Failed Weld-on illegal hot tap valve Crude oil theft (illegal bunkering Third party tampering with valve Corrosion Bulking Outward ipment impact	Hack saw cut Inward dent, e, Failed Clamp g) point, e setting, Saver-pit over flow	□ Exposed pipe surface □ Drill Rig □ Tear (with Clamp with flange, 3 rd party				
Relief valve failure □Others (specify) f. Incident caused by: □Third party interference (Sabotage, crude theft□; Line theft□; Accidental 3 rd party damage□) □Operational □Others (including Mystery spills)								
	Il point coordinates Measuring unit M Northing:	WINNA MID	- BE (T) Easting:					
SPI :	76 895.	81	535144	08				
SP2:	76 895. 76 892	31	535 143	63				

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 11353 49 JIV report S/N: 0427

C.	RISK ASSE	SSMENT				•			
	10.	Type of envi	ronment:						
	□ Łan	d □s	wamp [Water	Seaso	nal swamp 🗆 Si	horeline/Wat	erfront	
	i.	Type of envir	onment to whic	h oil has spreac	1:				
Land DSwamp DWater DRiver (identify)									
	ii.	Weather cond	lition						
	☐Rain 11. Distance		nny Cest sensitive hal	IDry □v oitat	Vet	□Windy	□Hot	□cool	
	□ Drii □ Bui □ Fari □ Fish □ Fish	nking water soo lt up area	ved and designa urce	ted protected a	теа	[HL ,m] [HL ,m] [HL ,m] [5 ,m] [HL ,m] [HL ,m]			
	12. Contain	ment measures	put in place;						
	□Boo		rench	Dyke	□Natur	al depression	⊠Pit		
	13. Any pict	tures or video o	coverage?			[Y] [N]			
	14. Was the	re any disruptio	on to the investi	gation?		[Y] \ [N]			
If ye	es give brief d	lescription:	N THE 6	" MNECH,	২ল4	Prassure	e was	<u>DBS</u>	7
<u>L</u> it	HIE ON	THE 7	TH - 9 TH	MARCH, 24	C14	Communi	M Die	STHEBANCE	_
>u	و تر ډ	atra 1	המאמנו	nc Don	our O	MIND INC	LRE nse	in Commun	Y
D. 7		BERS OF PRO		ANY, FOUN	D WITH	IN THE AREA	OF SPREA	D OF OIL	
S/N	Type of S	Structures	Description	Size	Number	-	Comments		
			_						
	ے بلے		L	\ \ \ \ \	ما		١	in ca	

16. Crops/Economic Trees

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1135349 JIV report S/N: 0427

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
L V_	CASSAUM			 -	₹6.W	CREP YELL
~	YAMS			_	FEW	WITHIN SPOC
						RIGHT OF
<u> </u>						Mr.
L	<u> </u>				=	

17. Fish/Nets/Ponds

REA	eF_	MPACT
	REA	REA OF


18. Others (Specify) i.e. Animal Traps

S/N Others	Description	Quantity/Size	Comments
HOHE W	THIN ARE	A of	IMPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTIONAL VIEW OF 24" NKPETCY - BOMY TRAINS NIGER PIPELINE
AT BINRA SHOWING: TWO ILLEGAL CUT AT 9" AND 12°CLOCK

POSITION:-



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1135349 JIV report S/N: 0427

19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

	MINHA MIE	- BETT)
S/N	Northing (M)	Easting (M)
WP 942	76 892.36	535 14 05
WYGY3	76 895.44	535 137, 97
WPGY		535 137. 98
W945	76 898.49	535 147, 22
N946	76 886-21	535 147 .20
W947	·	535 137 . 85
M948	76 834.01	535134.78
NG49	76 867 - 79	535141.01
		
 		
\longrightarrow		/
-		
-		
 		
\vdash		
/		
<u> </u>		_

G. INCIDENT INFORMATION:

20. Impacted Area Details

•	Total calculated area of impact_	<u> 11-0349.</u>	
•	Impact within SPDC R.O.W	YES	
•	Impact outside SPDC R.O.W	NO	

21. Volume of oil recovered before completion of JIV (V_{rect}):

	Recovered oil V _{reci} : 2	Barrels
a. Computatio	on of estimated residual volume on site on of estimated volume of pool of free phase oil (on land or confined water Area (m²) occupied by pool of free phase oil	body),
ii.	Average Depth (m) of pool of free phase oil	
iii.	Emulsification factor: 30 %	
iv.	Estimated Volume of pool of free phase oil.	barr
	V _{pool} 3.52	
	on of estimated volume of infiltrated oil in the soil (V _{inf}). mated Volume of infiltrated oil at spill point (Vinf a)	
i.	Area* (m²) of soil covered by the oil:	
ii.	Average Depth (m) above leaking facility i.e. pipeline/flowline: 1 · 2	- 3 M
iii.	Soil type: $Sil T$ iv. P_e (effective porosity of the soil). 2	
v.	Cause of spill: THERN PARTY. Oil type: RONN T MEDIUM	
vii.	Oil Residence time on site, day: Fiveshap	
viii.	Average depth of infiltration below leaking facility i.e. pipeline/flowline	: 0 · 0 05m
ix.	Estimated depth of infiltration around spill point: 1.205m	
	Estimated Volume of infiltrated oil at spill point. Vint. 3.1	& par
2. Estir	mated Volume of infiltrated oil at second spill point [if applicable] (Vinf b	·············)
i.	Area* (m²) of soil covered by the oil: 2 m²	
ii.	Average Depth (m) above leaking facility i.e. pipeline/flowline:	-
iii.	Soil type: \mathfrak{S}_{1} iv. P_{e} (effective porosity of the soil). \mathfrak{I}_{1}	
v.	Cause of spill: WERD PARTY VI. Oil type: BONNY MENUM	
vii.	Oil Residence time on site, day: Five Days	
viii.	Average depth of infiltration below leaking facility i.e. pipeline/flowline	0.005m
ix.	Estimated depth of infiltration around spill point: 1.205m ·	
	Estimated Volume of infiltrated oil at spill point Variant 3.18	barrels
3. E		
stima	ated Volume of infiltrated oil outside immediate spill point(s) region (Vin	fc)
i.	Area (m2) of soil covered by the oil: 227 m ²	
ii.	Area (m²) of the pool of free phase oil in touch with soil:	
iii.	Average Depth (m) below ground surface of infiltration of oil:	25m
iv.	Soil type: Sut	
v.	Pe (effective porosity of the soil). 21 10	
	vi. Estimated Volume of infiltrated oil. At Vinf.	27 ba

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1135349 JIV report S/N: 0427

ii. Table of average depth of oil on water based on coloration (

**Spill Factors from USCG FOG (2000 Edition)

•	Thickness (mm)	Percentage coverage	Volume (m3)
Barely Visible	0.00004	<u> </u>	
Silvery	0.00008	NONE	SECH
Slight Color	0.00015	1 ((
Bright Color	0.0003	WITH	i
Dull	0.001	Milli	
Dark	0.002	Mc	T
Black oil	0.1	qiciai	17.
Emulsion (30% Oil)	1		

iii. Estimated Volume of oil on open water. Vwai: Not APPLICABLE Barrels

24. Calculation of evaporated volume:

- i. Estimated Volume available for evaporation within surface area: 11 . 26 BARBER
- ii. E-Factor: 15%

iii. EstimatedVolume of evaporated oil. V_{evap}: [9] Barrels

Evaporation Factors (E-Factor) for SPDC Crude oil									
Oil Type Days on site Bonny Light Bonny Medium									
Oil Residence time	< 1 day	10%	5%						
	1-7 days	25%	15%						
	> 7 days	40%	25%						

25. Net Estimated Spilled Volume
$$V_{per}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{int}(bbls) + V_{pool}(bbls) + V_{rec}(bbls) = 1.99 + NIL + 7.73 + 3.52 + 2 = 15.24 Constant Const$$

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of I bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ------ Reported volume = 16 bbl Calculated volume = 0.35 bbl ------ Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ------ Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

26. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out

JOINT INVESTIGATION REPORT FOR INCIDENT NO	1135348	IIV romant C/NI.	0.497	,
JOINT INVESTIGATION REPORT FOR INCIDENTING	((3)3)4	JIV report S/N:	11477	1

В.	Investigation	of the	incident	site	showed	that	there	is	residual	impact	on	site	requiring	further
	works									7			. •	

27. REPRESENTATIVES

This report was filled, agreed and signed on the 10/03/20/14 by joint investigation representatives from

Host Community:

✓

OPR WAS PART OF THE ASSESSMENT BUT STARTED

Department of Petroleum Resources [DPR]:

remue AT completion of

- National Oil Spill Detection and Response Agency [NOSDRA]: S
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]: 5
- Shell Petroleum Development Company [SPDC]:
- Signatories agree with reported findings:

 ■
- Separate DPR form has been filled out with same findings□

Tick as applicable

28. Appendix 1: Overview sketch of the site

	Location:	<u>24"</u>	NAOKU	- Bomu	TRANS	NIGER	PIPELINE	F	BINEA.
٠1	•								
l									
				 					

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1135349 JIV report S/N: 0427 24" NKPUKY Bomy TRANS NIGER PIPELINE BINEA PLT. SPBC RIGHTUZE HIAY