



Close-up: Spill due to corrosion on 24" Bomu-Bonny Pipeline at Freetown. Picture was taken during Joint Investigation of 21st March 2014.