




Overview: Spill impact on Diebu creek Flowstation Right of Way at Peremabiri. Picture was taken during Joint Investigation of 20<sup>th</sup> May 2014.



Close-up: Spill due to failure of gas scrubber on Diebu creek Flowstation at Peremabiri. Picture was taken during Joint Investigation of 20<sup>th</sup> May 2014.