



Overview: Part of spill impact on Benisede –Akono Well1S Flowline Right of Way at Ojobo. Picture was taken during Joint Investigation of 8th May 2014.



Close-up: Spill due to corrosion on Benisede –Akono Well1S Flowline at Ojobo. Picture was taken during Joint Investigation of 28th May 2014.