



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at Ekporo. Picture was taken during Joint Investigation of 26<sup>th</sup> November 2014.



Close-up: Spill due to failed clamp on 28" Nkpoku-Bomu Pipeline at Ekporo. Picture was taken during Joint Investigation of 26<sup>th</sup> November 2014.