



Overview: General overview of Soku Well14S Wellhead at Soku showing no impact. Picture was taken during Joint Investigation of 30th December 2015.



Close-up: Leak from cut ends of Sensing Line on Soku Well14S Wellhead at Soku. Picture was taken during Joint Investigation of 30th December 2015.