

**THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.**

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1340664 JIV report S/N: 00836

*(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)*

**A. GENERAL INFORMATION:**

1. Spill incident Number: 1340664 2. Type of incident\* OIL SPILL  
 3. Name of Location 8" UMUECHEM - NIKPOKU PIPELINE  
 4. Name of nearest community OMUNIKET 5. State: RIVERS 6. LGA ETCHE  
 7. Type of Production facility/Installation OIL PIPELINE 8. Asset owner/District PIPELINE

**B. INCIDENT INFORMATION:**

9. Details of incident

- a. Date of incident: 18<sup>TH</sup> FEBRUARY, 2015  
 b. Start date/time of investigation: 20<sup>TH</sup> FEBRUARY, 2015 / 14:40 PM.  
 c. Investigation End date: 20<sup>TH</sup> FEBRUARY 2015 Actual investigation duration, days: ONE DAY.  
 d. Description of spill point environment

- |                                                   |                                                |                                                             |
|---------------------------------------------------|------------------------------------------------|-------------------------------------------------------------|
| <input type="checkbox"/> Firmed soil              | <input checked="" type="checkbox"/> Loose soil | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water              | <input type="checkbox"/> Swampy                | <input type="checkbox"/> Exposed pipe surface               |
| <input type="checkbox"/> Well Platform (on Water) |                                                | <input type="checkbox"/> Drill Rig                          |

Additional observations around the spill point: SAND BAGS WAS OBSERVED AT SPILL POINT. REMEDIATION ACTIVITIES WAS ALSO OBSERVED AROUND THE SPILL SITE. AS AT TIME OF JOINT INVESTIGATION VISIT THE 2" BALL VALVE HANDLE WAS IN OPEN POSITION.

c. Description of leak point (tick as applicable);

- |                                                                                |                                                         |                                                                     |
|--------------------------------------------------------------------------------|---------------------------------------------------------|---------------------------------------------------------------------|
| <input type="checkbox"/> Drilled hole                                          | <input type="checkbox"/> Hack saw cut                   | <input type="checkbox"/> Tear (_____).                              |
| <input type="checkbox"/> Complete Rupture                                      | <input type="checkbox"/> Inward dent,                   | <input type="checkbox"/> Well head tampering                        |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve,                 | <input type="checkbox"/> Failed Clamp                   | <input type="checkbox"/> Missing Pipeline/Flowline                  |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, |                                                         | <input type="checkbox"/> Third party tampering with Clamp           |
| <input type="checkbox"/> Third party tampering with valve setting,             |                                                         | <input type="checkbox"/> Third party tampering with flange,         |
| <input type="checkbox"/> Corrosion                                             | <input type="checkbox"/> Saver-pit over flow,           | <input type="checkbox"/> Surge vessel overflow,                     |
| <input type="checkbox"/> Bulging Outward                                       | <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Accidental 3 <sup>rd</sup> party equipment |
| impact                                                                         | <input type="checkbox"/> Valve Failure                  | <input type="checkbox"/> com unit failure                           |
| <input type="checkbox"/> Relief valve failure.                                 | <input type="checkbox"/> Others (specify) _____         | <input type="checkbox"/> Cold vent                                  |

f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3<sup>rd</sup> party damage   
 Operational  Others (including Mystery spills) \_\_\_\_\_

*\*This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire.*

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1340664 JIV report S/N: 00836

g. Spill point coordinates

Measuring unit	
Northing: (m)	Easting: (m)
108768.52	506947.29
/	/
/	/
/	/

MUNSA MID BELT

C. RISK ASSESSMENT

10. Type of environment:

- Land     Swamp     Water     Seasonal swamp     Shoreline/Waterfront

i. Type of environment to which oil has spread:

- Land     Swamp     Water     River (identify) \_\_\_\_\_

ii. Weather condition

- Rain     Sunny     Dry     Wet     Windy     Hot     cool

11. Distance from the nearest sensitive habitat

- Government reserved and designated protected area [ ,m]  
 Drinking water source [ ,m]  
 Built up area None seen [ ,m]  
 Farmlands within vicinity [ ,m]  
 Fish Farm/Pond [ ,m]  
 Fishing net [ ,m]  
 Others (specify).

12. Containment measures put in place:

- Booms     Trench     Dyke     Natural depression     Pit     None  
 Others: BOND WALL

13. Any pictures or video coverage? NY [N]

14. Further response/repair initiated as at the time of JIV? NY [N]

If yes to item 14, give brief description:

RECOVERY OF FREE PHASE OIL WAS DONE CONCURRENTLY WITH REPAIR ON THE AFFECTED SECTION OF THE PIPELINE.

15. Was there any disruption to the investigation? [Y] NY

If yes to item 15 give brief description:

NOT APPLICABLE.

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1340664 JIV report S/N: 00836

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

16. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	NONE WITHIN AREA OF IMPACT				

17. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	NONE WITHIN AREA OF IMPACT					

18. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	NONE WITHIN AREA OF IMPACT			

19. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	NONE WITHIN AREA OF IMPACT			

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTION OF 8" UMUECHEM - NKPORU PIPELINE AT OMUNKWES  
SHOWING CRUDE OIL THEFT POINT AT 12 O'CLOCK POSITION.



← FROM UMUECHEM TO NKPORU.



**THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.**

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1340664 JIV report S/N: 00836

**G. INCIDENT INFORMATION:**

20. Impacted Area Details

- Total calculated area of impact 0.006 Ha
- Impact within SPDC R.O.W YES
- Impact outside SPDC R.O.W NO

21. Volume of oil recovered before completion of JIV ( $V_{rec}$ ):

Recovered oil $V_{rec}$ :	<u>182</u>	Barrels
---------------------------	------------	---------

Controlled recovery/evacuation from source with no impact to environment:

<u>NIL</u>	Barrels
------------	---------

<b>22. Net Estimated Spilled Volume <math>V_{Est}(bbls)^*</math> =</b>	
<u>189 BARRELS</u>	
<b>Estimated Reported Volume** <math>V_{rep}(bbls)</math> =</b>	<u>189 BARRELS</u>

*\*Notes:*

- Volume estimation was done using an excel based tool, (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled in the box below:

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of  $m^3$  to barrels is Volume ( $m^3$ ) x 6.29; \*\*Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples:      Calculated volume = 15.3 bbl      ----- Reported volume = 16 bbl  
                     Calculated volume = 0.35 bbl      ----- Reported volume = 0.4 bbl  
                     Calculated volume = 0.01 bbl      ----- Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

**THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.**

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1340664 JIV report S/N: **00836**

**23. GENERAL STATUS OF THE SITE**

A. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/>
B. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/>

**24. REPRESENTATIVES**

<p>This report was filled, agreed and signed by the following joint investigation representatives:</p> <ul style="list-style-type: none"><li>• Host Community: <input checked="" type="checkbox"/></li><li>• Department of Petroleum Resources [DPR]: <input checked="" type="checkbox"/></li><li>• National Oil Spill Detection and Response Agency [NOSDRA]: <input checked="" type="checkbox"/></li><li>• State Ministry of Environment [SME]: <input checked="" type="checkbox"/></li><li>• Nigeria Police Force [NPF]: <input checked="" type="checkbox"/></li><li>• Shell Petroleum Development Company [SPDC]: <input checked="" type="checkbox"/></li><li>• Signatories agree with reported findings: <input checked="" type="checkbox"/></li><li>• Separate DPR form has been filled out with same findings <input checked="" type="checkbox"/></li></ul> <p style="text-align: right;"><i>Tick as applicable</i></p>
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1340664 JIV report S/N: 00836

25. Appendix 1: Overview sketch of the site

