



Overview: No visible impact on Bonny Terminal Single Point Mooring (SPM) 1 at Bonny. Picture was taken during Joint Investigation of 30th July 2015.



Close-up: Complete Rupture of Floating Hose 13 on Bonny Terminal Single Point Mooring (SPM) 1 at Bonny. Picture was taken during Joint Investigation of 23rd July 2015.