

# JOINT INVESTIGATION REPORT

INCIDENT NO: 1577647 JIV report S/N: Nº. 0000362

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

## A. GENERAL INFORMATION:

1. Spill incident Number: 1577647 2. Type of incident\* OIL SPILL  
3. Name of Location 20 INCH OPUKUSHI BRASS CREEK PIPELINE  
4. Name of nearest community TAMOGBENE 5. State: BAYELSA 6. LGA EKEREMOR  
7. Type of Production facility/Installation OIL PIPELINE  
8. Asset owner/District THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED / SWAMP WEST.

## B. INCIDENT INFORMATION:

### 9. Details of incident

- a. Date of incident: 18TH FEBRUARY 2016  
b. Start date/time of investigation: 21ST APRIL 2016 AT 1340HRS  
c. Investigation End date: 22ND APRIL 2016 Actual investigation duration, days: 2 DAYS  
d. Description of spill point environment

- |   |  |  |
|---|--|--|
| <input type="checkbox"/> Firm soil                | <input type="checkbox"/> Loose soil        | <input type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water              | <input checked="" type="checkbox"/> Swampy | <input type="checkbox"/> Exposed pipe surface    |
| <input type="checkbox"/> Well Platform (on Water) | <input type="checkbox"/> Drill Rig         |  |

Additional observations around the spill point: UPON EXCAVATION OF THE INCIDENT POINT, THE JOINT INVESTIGATION TEAM OBSERVED A FAILED 4 INCH VALVE ILLEGALLY ATTACHED TO THE 20 INCH OPUKUSHI - BRASS CREEK PIPELINE AT 12 O'CLOCK POSITION. LEAK AT THE INCIDENT POINT HAD STOPPED AS AT SECOND DAY OF INVESTIGATION.

### e. Description of leak point (tick as applicable):

- |  |   |  |
|--|---|--|
| <input type="checkbox"/> Drilled hole  | <input type="checkbox"/> Hack saw cut         | <input type="checkbox"/> Tear (_____).                                     |
| <input type="checkbox"/> Complete Rupture                                      | <input type="checkbox"/> Inward dent,         | <input type="checkbox"/> Well head tampering                               |
| <input checked="" type="checkbox"/> Failed Weld-on illegal hot tap valve       | <input type="checkbox"/> Failed Clamp,        | <input type="checkbox"/> Missing Pipeline/Flowline                         |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow  | <input type="checkbox"/> Third party tampering with Clamp                  |
| <input type="checkbox"/> Third party tampering with valve setting              | <input type="checkbox"/> Bulging Outward      | <input type="checkbox"/> Third party tampering with flange,                |
| <input type="checkbox"/> Flare System/Bund wall failure                        | <input type="checkbox"/> Cold vent            | <input type="checkbox"/> Surge vessel overflow,                            |
| <input type="checkbox"/> Valve Failure   | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 <sup>rd</sup> party equipment impact |
| <input type="checkbox"/> Others(specify) _____                                 |   |  |

### f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3<sup>rd</sup> party damage   
 Operational  Others (including Mystery spills) \_\_\_\_\_

\*This can be: a) Oil Spill b) Drilling fluid/Chemical c) Situation d) construction e) Encroachment f) Fire.

# JOINT INVESTIGATION REPORT

INCIDENT NO: 1577647 JIV report S/N: Nº 0000362

(THEFT POINT)

g. Spill point coordinates

WGS 84 (DECIMAL-DEGREE)

h. Measuring unit

Northing:	Easting:
4.941931	5.687008

## C. RISK ASSESSMENT

10. Type of environment:

- Land    
  Swamp    
  Water    
  Seasonal swamp    
  Shoreline/Waterfront

i. Type of environment to which oil has spread:

- Land    
  Swamp    
  Water    
  River (identify) \_\_\_\_\_

ii. Weather condition

- Rain    
  Sunny    
  Dry    
  Wet    
  Windy    
  Hot    
  cool

11. Distance from the nearest sensitive habitat

- Government reserved and designated protected area
- Drinking water source
- Built up area
- Farmlands
- Fish Farm/Pond
- Fishing net
- Others (specify).

[ .m]  
[ .m]  
[ .m]  
[ .m]  
[ .m]  
[ .m]

} NONE WITHIN  
THE VICINITY

12. Containment measures put in place:

- Booms    
  Trench    
  Dyke    
  Natural depression    
  Pit    
  None
- Others: COFFER-DAM

13. Any pictures or video coverage?

[ N ]

14. Further response/repair initiated as at the time of JIV?

[ Y ]

If yes to item 14, give brief description:

NOT APPLICABLE

15. Was there any disruption to the investigation?

[ Y ]

# JOINT INVESTIGATION REPORT

INCIDENT NO: 1577647 JIV report S/N: N<sup>o</sup> 0000362

If yes to item 15 give brief description: NOT APPLICABLE

**D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL**

**16. Structures / Properties**

S/N	Type of Structures	Description	Size	Number	Comments
	NONE	WITHIN		AREA	OF IMPACT

**17. Crops/Economic Trees**

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	NONE	WITHIN	AREA	OF	IMPACT	


**18. Fishing Nets/Fish Ponds**

S/N	Nets/Ponds	Description	Quantity/Size	Comments
	NONE	WITHIN	AREA	OF IMPACT

**19. Others (Specify) i.e. Animal Traps**

S/N	Others	Description	Quantity/Size	Comments
	NONE	SEEN	WITHIN	SITE VICINITY

**E. GRAPHIC DESCRIPTION OF LEAK POINT** (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)



20 INCH OPUKUSHI-BRASS CREEK PIPELINE AT TAMOGBENE

# JOINT INVESTIGATION REPORT

INCIDENT NO: 1577647 JIV report S/N: **Nº 0009362**

**F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION**

20. Impacted area boundary Coordinates (If more, Print and attach as an appendix)  
**WGS 84 (DECIMAL DEGREE)**

S/N	Northing	Easting
S.P.	4.941931	5.687008
	4.94206	5.68633
	4.94194	5.6868
	4.94185	5.68717
	4.94185	5.68726
	4.94201	5.65718
	4.94217	5.68636
	4.94194	5.68728
	4.94208	5.68683

# JOINT INVESTIGATION REPORT

Nº 9000362

INCIDENT NO: 1577647 JIV report S/N:

**G. INCIDENT INFORMATION:**

**a. Impacted Area Details**

- Total calculated area of impact 0.149 Ha
- Impact within R.O.W YES
- Impact outside R.O.W NO

**b. Volume of oil recovered before completion of JIV ( $V_{rec}$ ):**

Recovered oil $V_{rec}$ :	<u>NIL</u>	Barrels
---------------------------	------------	---------

Controlled recovery/evacuation from source with no impact to environment:

<u>NIL</u>	Barrels
------------	---------

**c. Net Estimated Spilled Volume  $V_{Est}$  (bbls)\* =**

113.51 BBLS

**Estimated Reported Volume\*\*  $V_{rep}$  (bbls) =**

114 BBLS

**\*Notes:**

- Volume estimation was done using an excel based tool. (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled in the box below:

NOT APPLICABLE.

*Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site. Conversion of m<sup>3</sup> to barrels is Volume (m<sup>3</sup>) x 6.29. \*\*Round up estimated volume to next whole number using the following rules:*

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

*Examples:      Calculated volume = 15.3 bbl      Reported volume = 16 bbl  
                     Calculated volume = 0.35 bbl      Reported volume = 0.4 bbl  
                     Calculated volume = 0.01 bbl      Reported volume = 0.1 bbl*

*Whenever this estimation tool is not applicable please refer to paragraph 6. (Deviations) of the JIV procedure to use appropriate steps for volume estimation; record the calculation in a plain sheet of paper and attach to the JIV report.*

# JOINT INVESTIGATION REPORT

INCIDENT NO: 1577647 JIV report S/N: N<sup>o</sup> 0000362

## d. General Status of the site

i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out

ii. Investigation of the incident site showed that there is residual impact on site requiring further works

## e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:

- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Asset Owner:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings:

*Tick as applicable*

# JOINT INVESTIGATION REPORT

INCIDENT NO: 1577647 JIV report S/N: № 0000362

f. Appendix I: Overview sketch of the site

