

JOINT INVESTIGATION REPORT

INCIDENT NO: 1595255 JIV report S/N: 1 N° 0000137

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:

- | | |
|---|---|
| 1. Spill incident Number: <u>1595255</u> | 2. Type of incident* <u>OIL SPILL</u> |
| 3. Name of Location <u>36" NKOKU - BONU TRANS NIGER PIPELINE</u> | |
| 4. Name of nearest community <u>RUMUCHIDU</u>
<u>EKEKA</u> | 5. State: <u>RIVERS</u> 6. LGA <u>OBIO AKPO</u> |
| 7. Type of Production facility/Installation <u>OIL PIPELINE</u> | |
| 8. Asset owner/District <u>THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED</u> | |

B. INCIDENT INFORMATION:

- | |
|---|
| 9. Details of incident |
| a. Date of incident: <u>15th MARCH, 2016</u> |
| b. Start date/time of investigation: <u>22nd March, 2016</u> |
| c. Investigation End date: <u>22nd MARCH, 2016</u> Actual investigation duration, days: <u>ONE DAY</u> |
| d. Description of spill point environment |

- | | | |
|---|-------------------------------------|---|
| <input type="checkbox"/> Firm soil | <input type="checkbox"/> Loose soil | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water | <input type="checkbox"/> Swampy | <input type="checkbox"/> Exposed pipe/surface |
| <input type="checkbox"/> Well Platform (on Water) | <input type="checkbox"/> Drill Rig | |

Additional observations around the spill point: THE JOINT INVESTIGATING TEAM OBSERVED THAT THE INCIDENT POINT IS VERY CLOSE TO SURVEILLANCE HUT.

e. Description of leak point (tick as applicable):

- | | | |
|--|---|--|
| <input type="checkbox"/> Drilled hole | <input type="checkbox"/> Hack saw cut | <input type="checkbox"/> Tear (_____) |
| <input type="checkbox"/> Complete Rupture | <input type="checkbox"/> Inward dent, | <input type="checkbox"/> Well head tampering |
| <input checked="" type="checkbox"/> Failed Weld-on illegal hot tap valve | <input type="checkbox"/> Failed Clamp, | <input type="checkbox"/> Missing Pipeline/Flowline |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point. | <input type="checkbox"/> Saver-pit over flow | <input type="checkbox"/> Third party tampering with Clamp |
| <input type="checkbox"/> Third party tampering with valve setting | <input type="checkbox"/> Bulging Outward | <input type="checkbox"/> Third party tampering with flange, |
| <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Cold vent | <input type="checkbox"/> Surge vessel overflow, |
| <input type="checkbox"/> Valve Failure | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 rd party equipment impact |
| <input type="checkbox"/> Others(specify) _____ | | |

f. Incident caused by:

- | |
|---|
| <input checked="" type="checkbox"/> Third party interference (Sabotage <input type="checkbox"/> crude theft <input type="checkbox"/> Line theft <input type="checkbox"/> Accidental 3 rd party damage <input type="checkbox"/>) |
| <input type="checkbox"/> Operational <input type="checkbox"/> Others (including Mystery spills) _____ |

*This can be: a) Oil Spill b) Drilling fluid Chemical c) Silation d) construction e) Encroachment f) Fire.

JOINT INVESTIGATION REPORT

INCIDENT NO: 1595255 JIV report S/N: Nº 0000137

g. Spill point coordinates

h. Measuring unit NGVD 84

Northing:	Lat	Easting:	Long
4921897		7138363	

C. RISK ASSESSMENT

10. Type of environment:

Land Swamp Water Seasonal swamp Shoreline/Waterfront

i. Type of environment to which oil has spread:

Land Swamp Water River (identify) _____

ii. Weather condition

Rain Sunny Dry Wet Windy Hot cool

11. Distance from the nearest sensitive habitat

- Government reserved and designated protected area
- Drinking water source
- Built up area
- Farmlands
- Fish Farm/Pond
- Fishing net
- Others (specify). _____

[] , [m]
 [] , [m]

{
 NONE SEEN
 WITHIN
 VICINITY

12. Containment measures put in place:

Booms Trench Dyke Natural depression Pit None

Others: _____

13. Any pictures or video coverage?

[Y] [N]

14. Further response/repair initiated as at the time of JIV?

[Y] [N]

If yes to item 14, give brief description:

NO RECOVERABLE OIL, WHILE REPAIR

WORK IS ON-GOING

15. Was there any disruption to the investigation?

[Y] [N]

JOINT INVESTIGATION REPORT

INCIDENT NO: 1595255 JIV report S/N: No. 0000137

If yes to item 15 give brief description:

NOT APPLICABLE

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

16. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
					<u>NONE WITHIN AREA OF IMPACT</u>

17. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
						<u>NONE WITHIN AREA OF IMPACT</u>

18. Fishing Nets/Fish Ponds


S/N	Nets/Ponds	Description	Quantity/Size	Comments
				<u>NONE WITHIN AREA OF IMPACT</u>

19. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
				<u>NONE WITHIN AREA OF IMPACT</u>

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTIONAL VIEW OF 36" NKPOKU - BOMI TRANS NIGER PIPELINE AT RUMBOCHI
- ENEKA SHOWING :- A FAILED WELD - EN ILLEGAL THEFT POINT.



JOINT INVESTIGATION REPORT

INCIDENT NO: 1595255 JIV report S/N: N° 0000137

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

20. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

ESTIMATION OF OIL SPILL VOLUME

FID =1595255 AT 38" NKPOKU BOMU TRANS NIGER PIPELINE AT RUMUOCHIOLU ENEKA JV VOLUME CALCULATION REPORT

A OIL SPILLED ONSHORE/OFFSHORE (Leak stopped at source)**Impacted Area Details**

Total Calculated Area of Impact

64.00	m ²
	m ²
	m ²

i Impact within SPDC R.O.W

ii Impact outside SPDC R.O.W

1 Volume of oil recovered before completion of JV (V_{recd})

i Estimated Recovered oil (Net)

[] bbls

Estimated Recovered oil (Net) V_{recd}

0.00 bbls

2 Computation of estimated residual volume on site**a Computation of volume of free phase oil (on land or confined water body)**

i Total area occupied by pool of free phase oil

[] m²

ii Average depth of pool of free phase oil

[] m

iii Emulsification factor (If applicable, else 0%)

[] 30%

Estimated Volume of pool of free phase oil, V_{pool}[] m³Estimated Volume of pool of free phase oil, V_{pool}

0.00 bbls

b Computation of estimated volumes of infiltrated oil in the soil (V_{inf})i Volume of infiltrated oil at spill point (V_{inf1})[] m²

i Total area covered by the oil (infiltration)

[] m

ii Average depth of infiltration above leaking facility i.e. pipeline/flowline

[] m

iii Soil type

Silty or sandy clay

iv P_e (effective porosity of the soil)

[] 12%

v Cause of spill

Third party interference

vi Calculation of days for infiltration below the leaking point on pipeline or flowline

Incident Date	JV Date	Days on Site
3/15/2016 13:40	3/22/2016 14:45	7
If 'cause of spill' is 'operational', use 1 week as worst case scenario except where 'Days on site' exceeds 7		7

Infiltration of oil types in various soil types vs time.

Soil type	Approximate time to reach 1m depth below ground level		
	Sand	Loam	Clay
Bony Medium	3 weeks	3 years	> 10 years
Bony Light	2 days	2 months	> 10 years

vii Oil type

[]

viii Average depth of infiltration below leaking facility i.e. pipeline/flowline

[] m

ix Total depth below ground surface of infiltration of oil

[] m

Estimated Volume of infiltrated oil, V_{inf1}[] m³Estimated Volume of infiltrated oil, V_{inf1}

0.16 bbls

2 Volume of infiltrated oil at second spill point [if applicable] (V_{inf2})

i Total area covered by the oil (infiltration)

[] m²

ii Average depth of infiltration above leaking facility i.e. pipeline/flowline

[] m

iii Soil type

Silty or sandy clay

iv P_e (effective porosity of the soil)

[] 12%

v Average depth of infiltration below leaking facility i.e. pipeline/flowline

[] m

vi Total depth below ground surface of infiltration of oil

[] m

Estimated Volume of infiltrated oil, V_{inf2}[] m³Estimated Volume of infiltrated oil, V_{inf2}

0.00 bbls

3 Volume of infiltrated oil outside immediate spill point(s) region (V_{inf3})

i Total Area covered by the oil (infiltration)

[] m²

ii Total Area of the pool of free phase oil in touch with soil

[] m²

34.00

JOINT INVESTIGATION REPORT SPILL VOLUME ESTIMATE FOR INCIDENT NO.: 1595255

iii Soil type	Silty or sandy clay		
iv P_e (effective porosity of the soil)	%		
v Average depth below ground surface of infiltration oil	m		
Estimated Volume of infiltrated oil, $V_{inf,c}$	0.01 m ³		
Estimated Volume of infiltrated oil, $V_{inf,c}$	0.06 bbls		
4 Volume of infiltrated oil outside immediate spill point(s) region (superficial impact, $V_{inf,d}$)			
i Total Area covered by the oil (infiltration)	m ²		
ii Total Area of the pool of free phase oil in touch with soil	m ²		
iii Average depth below ground surface of infiltration oil	m		
Estimated Volume of infiltrated oil, $V_{inf,d}$	0.00 m ³		
Estimated Volume of infiltrated oil, $V_{inf,d}$	0.00 bbls		
Estimated Total Volume of infiltrated oil, V_{inf}	0.03 m ³		
Estimated Total Volume of infiltrated oil, V_{inf}	0.20 bbls		
c Computation of volume of oil on open water based on standard coloration			
i Total area of oil on open water	m ²		
ii Table of average depth of oil on water based on coloration	Link to Coverage Visual		
Spill Factors from USCG FOG (2008 Edition)			
	Thickness (mm)	Percentage coverage (%)	Volume (m ³)
Barely Visible	0.00004		0.0000
Silvery	0.00008		0.0000
Slight Color	0.00015		0.0000
Bright Color	0.0003		0.0000
Dull	0.001		0.0000
Dark	0.002		0.0000
Black oil	0.1		0.0000
Emulsion (30% Oil)	1		0.0000
Percent Total:	0%		0.0000
Estimated Volume of oil on open water, V_{ow}	0.00 m ³		
Estimated Volume of oil on open water, V_{ow}	0.00 bbls		

3 Calculation of evaporated volume

Evaporation Factors (E-Factor) for SPDC Crude oil		
Residence time of spilled oil (days on site)	Oil type	
	Bonny Light	Bonny Medium
< 1 day	10%	5%
1-7 days	25%	15%
> 7 days	40%	25%

i Was oil recovery before JV completion done before JV date?	No
ii Estimated volume available for evaporation	0.45 bbls
iii E-factor	25 %
Estimated Volume of evaporated oil, V_{evap}	0.15 bbls
Net Total Estimated Spilled Volume, V_{est}	0.60 bbls

JOINT INVESTIGATION REPORT

INCIDENT NO: 1595255 JIV report S/N: No 0000137

G. INCIDENT INFORMATION:

a. Impacted Area Details

- Total calculated area of impact 0.006324 ha
- Impact within R.O.W YES
- Impact outside R.O.W N.L

b. Volume of oil recovered before completion of JIV (V_{rec}):

Recovered oil V_{rec} :	<u>Nil</u>	Barrels
---------------------------	------------	---------

Controlled recovery/evacuation from source with no impact to environment:

<u>Nil</u>	Barrels
------------	---------

c. Net Estimated Spilled Volume $V_{est}(bbis)^*$ =

0.6 BARREL

Estimated Reported Volume** $V_{rep}(bbis) =$

0.6 BARREL

*Notes:

- Volume estimation was done using an excel based tool (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled in the box below:

NOT APPLICABLE

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site:
Conversion of m³ to barrels is Volume (m³) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume 15.3 bbl Reported volume 16 bbl
 Calculated volume 0.35 bbl Reported volume 0.4 bbl
 Calculated volume 0.01 bbl Reported volume 0.1 bbl

Whenever this estimation tool is not applicable please refer to paragraph 6.1 Deviations of the JIV procedure to take appropriate steps for volume estimation, record the calculation in a plain sheet of paper and attach to the JIV report.

JOINT INVESTIGATION REPORT

INCIDENT NO: 1595255 JIV report S/N: N° 0000137

d. General Status of the site

- i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out
- ii. Investigation of the incident site showed that there is residual impact on site requiring further works

e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:


- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Asset Owner:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings:

Tick as applicable

JOINT INVESTIGATION REPORT

INCIDENT NO: 1595255 JIV report S/N: Nº 0000137

f. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT

INCIDENT NO: 1595255 JIV report S/N: N° 0000137

g. SIGNATORIES: JOINT INVESTIGATION TEAM MEMBERS

Having read through the JIT report, the following representatives append their respective signatures in agreement with the content therein:

S/N	Name	Members present	Designation	Signature/Date and Time
1	//	DEPARTMENT OF PETROLEUM RESOURCES (DPR)	//	//
2	OBA ABUBAKAR .O	NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY (NOSDRA)	P.S.I	<i>Day 150 1330hrs 22/03/2016</i>
3	Ejobe Iforft	STATE MIN. OF ENVIRONMENT	S.C. Eng.	<i>G. J. Iforft 22/3/2016</i>
4	Godwin & Ngezi OWUONWAH	HOST COMMUNITY REPRESENTATIVE	FIN. SEC. C.D.C	<i>Samuel. 22.3/2016</i>
5	Otis OKTUESE	ASSET OWNER REPRESENTATIVE	PNP D	<i>Samuel 22/3/16</i>
6	SAMSON ILIYA	NIGERIA POLICE FORCE (NPF)	INSPR.	<i>1530 HRS 22/3/16</i>
	//	//	//	//