



**Overview:** Part of spill impact on 6" Kanbo Wells 7S and 9T Flowlines at Agbidiama. Picture was taken during Joint Investigation of 26<sup>th</sup> October 2016.



**Close-up:** Illegally attached flexible hose and 6" valve on 6" Kanbo Well 7S Flowline at Agbidiama. Picture was taken during Joint Investigation of 26<sup>th</sup> October 2016.



**Close-up: Illegally attached 3" valve on 6" Kanbo Well 9T Flowline at Agbidiama. Picture was taken during Joint Investigation of 26<sup>th</sup> October 2016.**