




Overview: Part of spill impact on 28" Bomu-Bonny Pipeline Right of Way at Ogbonga Forest Oloma. Picture was taken during Joint Investigation of 13th September 2017.



Close-up: Non leaking illegal fitting on 28" Bomu-Bonny Pipeline at Ogbonga Forest Oloma. Picture was taken during Joint Investigation of 13th September 2017.



Close-up: Illegal pipe and failed 2" ball valve hose connection on 28" Bomu-Bonny Trans Niger Pipeline at Ogbonga Forest Oloma. Picture was taken during Joint Investigation of 13th September 2017.



Close-up: Leak point on 28" Bomu-Bonny Pipeline at Ogbonga Forest Oloma. Picture was taken during Joint Investigation of 13th September 2017.