




Overview: Part of spill impact 01 MOV-411 Filling Valve Flange to Tank 2 at Bonny Terminals. Picture was taken during Joint Investigation of 29th September 2017.



Close-up: Leaking Flange on 01 MOV-411 Filling Valve Flange to Tank 2 at Bonny Terminals. Picture was taken during Joint Investigation of 29th September 2017.