INCIDENT NO: 2005 045 JIV report S/N: 0990

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 1. Spill incident Number: 2005045 \$2. Type of incident* O/L SPILL 3. Name of Location 4" GRARAN WELL 12.7 FLOWLINE 4. Name of nearest community ONOPA 5. State: BAYELSA 6. LGA YENAGOA 7. Type of Production facility/Installation FLOWLINE 8. Asset owner/District THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LT. (SPAC)/CENTRAL HUB B. INCIDENT INFORMATION: 9. Details of incident a. Date of incident: 22ND JANUARY 2018 b. Start date/time of investigation: 24TH JANUARY 2018/1200HRS c. Investigation End date: 24 TH JANUARY 2018 Actual investigation duration, days: ONE (1) DAY d. Description of spill point environment Loose soil ☐Firm soit Recently excavated area Under water □Swampy 1 ☐ Exposed pipe surface ☐Well Platform (on Water) □Drill Rig Additional observations around the spill point: THE JOINT INVESTIGATION HACK SAW ZUTS. AT 10'0'CLOCK POSITION POSITION e. Description of leak point (tick as applicable); ☐ Drilled hole Ilack saw cut Tear (Complete Rupture Inward dent. ☐ Well head tampering ☐Failed Weld-on illegal hot tap valve Failed Clamp, ☐ Missing Pipeline/Flowline ☐Crude oil theft (illegal bunkering) point, ☐ Saver-pit over flow ☐ Third party tampering with Clamp ☐ Third party tampering with valve setting Bulging Outward ☐ Third party tampering with flange, ☐ Flare System/Bund wall failure Cold vent ☐ Surge vessel overflow, ☐ Valve Failure Relief valve failure Accidental 3rd party equipment impact ☐ Corrosion Others(specify)_ f. Incident caused by: Third party interference (Sabotago ; crude the ft : Line the ft : Accidental 3rd party damage : ☐ Operational ☐ Mystery spills ☐ Others(specify)_

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical e) Siltation d) construction e) Encroachment f) Fire,

JIV report S/N: 0990 INCIDENT NO: 2005045 g. Spill point coordinates WGS 84 h. Measuring unit Northing: & DUTIBNO 50 VT1 FA-1 C. RISK ASSESSMENT 10. Type of environment; \\D\Land Swamp □Water ☐ Seasonal swamp ☐ Shoreline/Waterfront i. Type of environment to which oil has spread: Land River (identify). Swamp □Water ii. Weather condition Rain Sunny **√**Drv . Wet ☐ Windy □Hot Cool 11. Distance from the nearest sensitive habitat ☐ Government reserved and designated protected area ,mj Drinking water source ,m] NONE SEEN □ Built up area ,ոո] □ Farmlands ,m] WITHIN VICINITY □ Fish Farm/pond □ Fishing net VI Others (specify). TARRED ROAD 12. Containment measures put in place; Dyke √**Z**Pit □None ☐ Booms Trench ☐ Natural depression Others: 13. Any pictures or video coverage? 14. Further response/repair initiated as at the time of JIV? if yes to item 14, give brief description: RECOVERY

[Y]

([M]

15. Was there any disruption to the investigation?

If yes to item 15 give brief description:

INCIDENT NO: 2005045 JIV report S/N: 0990

$\frac{100}{100}$	7112	107	10~				
D. TYPE/NUMBERS OF		ANY, FOUND	WITHIN THE	AREA O	F SPREA	D OF OIL	
S/N Type of Structure		Size	Numbe	r		Comments	
NONE	NITHI	W A	REA	OF.	M	PACT	
17. Crops/Economic T	rees						
S/N Type of crops	Young	Medium	Matured	Qua	ntity	Comments	
MONE W	THIN	ARE	A OF	//\	1PA	C7	
18. Fishing Nets/Fish	Ponds				-		
S/N Nets/Ponds	Descrip	tion	Quantity/Size	•	Comments		
NONE W	THIN #	RE	¥ OF	-/M	MPACT		
19. Others (Specify) i. S/N Others	e. Animal Traps Descrip	tion	Quantity/Size		Comm	ents	
NONEV	VITHIN	ARE	A OF	- IM	PAI		
E. GRAPHIC DESCRIPTION OF THE leak report, overvious IELL 12T FLOWER	ew <mark>sketch of the site s</mark>	hould be added	l <mark>as</mark> an <mark>appendi</mark> x l	9 2. 🕰 (CTIOI	Y OF 4" GBA	
LMETERS APA						POSITION	
SPILL POINT/ HACK SAW CUT D'CLOCK POSITIO	AT		HA.	SPIL CKSAN OSITI	VCUT	INT/ AT 10 D'CLOC	

GRARAN WELL IZ TO FLOW STATION PAGE 3 018

48

INCIDENT NO: 2005045 JIV report S/N: 0990

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

20. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

_		2 & ሲ
S/N	Northing LATITUDE	Easting LONGITUDE
١.	4.98678	6 30930
ゔ	4.98689	6 30938
3.	4.98698	6.30935
4.	4.98698	6.30932
<u></u> 5.	4.98694	6.30930
60	4.98695	6.30925
7-	4.98693	6.30922
8.	4-98683	6.369(1
9.	4-98678	6.30925
10-	4.98692	6.30937
].
		·

กรรก

INCIDENT NO: 2005045 JIV report	s/N: 0990
. INCIDENT INFORMATION:	
a. Impacted Area Details	
• Total calculated area of impact 0.0444	·
• Impact within R.O.W	· · · · · · · · · · · · · · · · · · ·
Impact outside R.O.W	
b. Volume of oil recovered before completion of JIV (Vreed):	
Controlled recovery/evacuation from source with no impact to environment:	Barrels
c. Net Estimated Spilled VolumeV _{Est} (bbls)* =	
2.33 BARI	KELS
stimated Reported Volume** Vren(bbls)= 3 BARRELS	
Notes: Volume estimation was done using an excel based tool (see attached for details on the calculation) Reported spilled volume is an estimate	
Write other relevant notes taken into consideration for estimating the spilled in the box below:	

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site:

Conversion of m^t to barrels is Volume:(m3) x 6.29: **Round up estimated volume to next whole number using the following rules:

Any spill volume in excess of | l bb| is rounded up to the next whole number:

- Any spill volume in less than I bbl is rounded up to the next 0.1 bbl.

Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl Examples: Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl

Wherever this estimation tool is not applicable please refer to paragraph 6e (Deviations) of the HV procedure to use appropriate steps for . volume estimation: record the calculation in a plain sheet of paper and attach to the JIV report.

INCIDENT NO: 2005045 JIV report S/N: 0990
d. General Status of the site
i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out
ii. Investigation of the incident site showed that there is residual impact on site requiring further works.
e. Representatives
This report was filled, agreed and signed by the following joint investigation team representatives:
■ Host Community. ☑
Department of Petroleum Resuurces [DPR]:
National Oil Spill Detection and Response Agency [NOSDRA]
State Ministry of Environment [SME]
Asset Owner*
Signatories agree with reported findings
Separate DPR form has been filled out with same findings
Tick as applicable

INCIDENT NO: 2005045 JIV report S/N: 0990

f. Appendix 1: Overview sketch of the site

