

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2107841 JIV report S/N: 1098

(Note: As practicable as possible the JIV report is to be signed in the field by all the participating parties)

## A. GENERAL INFORMATION:

1. Spill incident Number: 2107841 2. Type of incident\* OIL SPILL  
3. Name of Location 14" ORORDIA - RUMUEKPE PIPELINE  
4. Name of nearest community AKARA - MINI 5. State: RIVERS 6. LGA AHOADA WEST  
7. Type of Production facility/Installation OIL PIPELINE  
8. Asset owner/District THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LTD (SPDC) / PIPELINE

## B. INCIDENT INFORMATION:

### 9. Details of incident

- a. Date of incident: 27TH JUNE 2018  
b. Start date/time of investigation: 3RD JULY 2018 / 1100 HRS  
c. Investigation End date: 6TH JULY 2018 Actual investigation duration, days: THREE (3) DAYS  
d. Description of spill point environment

- |   |  |   |
|---|--|---|
| <input type="checkbox"/> Firm soil                | <input checked="" type="checkbox"/> Loose soil | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water              | <input type="checkbox"/> Swampy                | <input type="checkbox"/> Exposed pipe surface               |
| <input type="checkbox"/> Well Platform (on Water) | <input type="checkbox"/> Drill Rig             |   |

Additional observations around the spill point: THE JOINT INVESTIGATION TEAM SAW EVIDENCE OF MISSING CLAMP, FROM PREVIOUS INCIDENT OF DRILLED HOLE AT 4 O'CLOCK POSITION.

### e. Description of leak point (tick as applicable);

- |   |  |  |
|---|--|--|
| <input type="checkbox"/> Drilled hole                               | <input type="checkbox"/> Hack saw cut                                    | <input type="checkbox"/> Tear (_____)                                      |
| <input type="checkbox"/> Complete Rupture                           | <input type="checkbox"/> Inward dent,                                    | <input type="checkbox"/> Well head tampering                               |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve       | <input type="checkbox"/> Failed Clamp,                                   | <input type="checkbox"/> Missing Pipeline/Flowline                         |
| <input type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow                             | <input type="checkbox"/> Third party tampering with Clamp                  |
| <input type="checkbox"/> Third party tampering with valve setting   | <input type="checkbox"/> Bulging Outward                                 | <input type="checkbox"/> Third party tampering with flange,                |
| <input type="checkbox"/> Flare System/Bund wall failure             | <input type="checkbox"/> Cold vent                                       | <input type="checkbox"/> Surge vessel overflow,                            |
| <input type="checkbox"/> Valve Failure                              | <input type="checkbox"/> Relief valve failure                            | <input type="checkbox"/> Accidental 3 <sup>rd</sup> party equipment impact |
| <input type="checkbox"/> Corrosion                                  | <input checked="" type="checkbox"/> Others(specify) <u>MISSING CLAMP</u> |  |

### f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3<sup>rd</sup> party damage   
 Operational  Mystery spills  Others(specify) \_\_\_\_\_

\*This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2107841 JIV report S/N: 1098

g. Spill point coordinates

h. Measuring unit

WGS 84

Northing: <u>LATITUDE</u>	Easting: <u>LONGITUDE</u>
<u>5.11860</u>	<u>6.48885</u>
/	/
/	/

### C. RISK ASSESSMENT

10. Type of environment:

- Land    
  Swamp    
  Water    
  Seasonal swamp    
  Shoreline/Waterfront

i. Type of environment to which oil has spread:

- Land    
  Swamp    
  Water    
  River (identify) \_\_\_\_\_

ii. Weather condition

- Rain    
  Sunny    
  Dry    
  Wet    
  Windy    
  Hot    
  cool

11. Distance from the nearest sensitive habitat

- Government reserved and designated protected area [     ,m]
- Drinking water source [     ,m]
- Built up area [     ,m]
- Farmlands [ 50 ,m]
- Fish Farm/pond [     ,m]
- Fishing net [     ,m]
- Others (specify) [     ,m]

12. Containment measures put in place;

- Booms    
  Trench    
  Dyke    
  Natural depression    
  Pit    
  None
- Others: \_\_\_\_\_

13. Any pictures or video coverage?

[N]

14. Further response/repair initiated as at the time of JIV?

[N]

if yes to item 14, give brief description:

LEAK REPAIR

15. Was there any disruption to the investigation?

[Y]

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2107841 JIV report S/N: 1098

If yes to item 15 give brief description:

NOT APPLICABLE

**D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL**

**16. Structures / Properties**

S/N	Type of Structures	Description	Size	Number	Comments
<u>NONE WITHIN AREA OF IMPACT</u>					

**17. Crops/Economic Trees**

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
1	PALM TREES	2			2	IMPACTED
<u>NONE WITHIN AREA OF IMPACT</u>						

**18. Fishing Nets/Fish Ponds**


S/N	Nets/Ponds	Description	Quantity/Size	Comments
<u>NONE WITHIN AREA OF IMPACT</u>				

**19. Others (Specify) i.e. Animal Traps**

S/N	Others	Description	Quantity/Size	Comments
<u>NONE WITHIN AREA OF IMPACT</u>				

**E. GRAPHIC DESCRIPTION OF LEAK POINT** (While detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix I) A SECTION OF 14" OKORDIA - RUMUEKPE PIPELINE AT AKARA-MINI SHOWING EVIDENCE

OF MISSING CLAMP FROM PREVIOUS DRILLED HOLE INCIDENT, REMOVED BY UNKNOWN PERSON(S)





14" OKORDIA - RUMUEKPE PIPELINE AT AKARA-MINI		
INCIDENT NUMBER : 2107841		
PT_ID	LAT_Y	LONG_X
170	5.1186	6.48885
164	5.11858	6.48872
165	5.11859	6.48878
166	5.11859	6.48883
167	5.11918	6.48955
168	5.11851	6.48887
169	5.1185	6.48882
171	5.11862	6.48888
172	5.11875	6.4889
173	5.11877	6.4889
174	5.1194	6.4893
175	5.11929	6.48933
176	5.11932	6.48933
177	5.11915	6.48934
178	5.11908	6.48946
179	5.1191	6.48952
180	5.11917	6.48896
181	5.11857	6.48887
182	5.11847	6.48881
183	5.11918	6.48947
184	5.1193	6.48942
185	5.11954	6.48938
186	5.11944	6.48947
187	5.11958	6.48926
188	5.11941	6.48907
189	5.1192	6.48894
190	5.11911	6.48876
191	5.11892	6.48884
192	5.11909	6.48881
193	5.11891	6.48881
194	5.11935	6.4891
195	5.11875	6.48886
196	5.11863	6.48885

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2107841 JIV report S/N: 1098

**G. INCIDENT INFORMATION:**

**a. Impacted Area Details**

- Total calculated area of impact 0.1707 Ha
- Impact within R.O.W YES
- Impact outside R.O.W YES

**b. Volume of oil recovered before completion of JIV ( $V_{rec}$ ):**

Recovered oil $V_{rec}$ :	<u>NIL</u>	Barrels
---------------------------	------------	---------

Controlled recovery/evacuation from source with no impact to environment:

<u>NIL</u>	Barrels
------------	---------

**c. Net Estimated Spilled Volume  $V_{Est}$  (bbls)\* =**

	<u>16.35 BARRELS</u>
<b>Estimated Reported Volume** <math>V_{rep}</math> (bbls) =</b>	<u>17 BARRELS</u>

**\*Notes:**

- Volume estimation was done using an excel based tool. (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled in the box below:

/

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site: Conversion of  $m^3$  to barrels is Volume: ( $m^3$ ) x 6.29: \*\*Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number:
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl — Reported volume = 16 bbl  
 Calculated volume = 0.35 bbl — Reported volume = 0.4 bbl  
 Calculated volume = 0.01 bbl — Reported volume = 0.1 bbl

Wherever this estimation tool is not applicable please refer to paragraph 6e (Deviations) of the JIV procedure to use appropriate steps for volume estimation: record the calculation in a plain sheet of paper and attach to the JIV report.

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2107841 JIV report S/N: 1098

## d. General Status of the site

- i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out
- ii. Investigation of the incident site showed that there is residual impact on site requiring further works

## e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:

- Host Community
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]
- State Ministry of Environment [SME]:
- Asset Owner:
- Signatories agree with reported findings
- Separate DPR form has been filled out with same findings

*Tick as applicable*

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2107841 JIV report S/N: 1098

f. Appendix 1: Overview sketch of the site

