



Overview: Part of spill impact on 4" Imo River 2 Well 21S Flowline at Odagwa. Picture was taken during Joint Investigation of 8th November 2018.



Close-up: Section of Missing Flowline on 4" Imo River 2 Well 21S Flowline at Odagwa. Picture was taken during Joint Investigation of 8th November 2018