

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2530938 JIV report S/N: 1030191

*(Note: As practicable as possible the JIV report is to be signed in the field by all the participating parties)*

**A. GENERAL INFORMATION:**

1. Fountain Incident Number: 2530938 2. Type of incident\* OIL SPILL  
 3. Name of Location 12" IMO RIVER 2 PIPELINE AT UMUOLOLO  
 4. Name of nearest community UMUOLOLO 5. State: ABIA 6. LGA UKWA WEST  
 7. Type of Production facility/Installation OIL PIPELINE  
 8. Asset owner/District: THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED (SPDC) (PIPELINE)

**B. INCIDENT INFORMATION:**

9. Details of incident  
 a. Date Reported: 16<sup>TH</sup> DECEMBER, 2019  
 b. Start date/time of investigation: 18<sup>TH</sup> DECEMBER, 2019, 1315 HRS  
 c. Investigation End date: 18<sup>TH</sup> DEC, 2019 Actual investigation duration, days: ONE DAY  
 d. Description of spill point environment

- |  |  |   |
|--|--|---|
| <input type="checkbox"/> Firm soil               | <input checked="" type="checkbox"/> Loose soil | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water             | <input type="checkbox"/> Swampy                | <input type="checkbox"/> Exposed pipe surface               |
| <input type="checkbox"/> Well Platform (on Water | <input type="checkbox"/> Drill Rig             |   |

Additional observations around the spill point: JOINT INVESTIGATION TEAM OBSERVED THAT LEAK IS FROM A PREVIOUSLY REPORTED NON-LEAKING ILLEGAL CONNECTION/THEFT LINE. (REF ID- 2500035)

**e. Description of leak point (tick as applicable);**

- |  |   |  |
|--|---|--|
| <input type="checkbox"/> Drilled hole  | <input type="checkbox"/> Hack saw cut         | <input type="checkbox"/> Tear ( _____ ),                                   |
| <input type="checkbox"/> Complete Rupture                                      | <input type="checkbox"/> Inward dent,         | <input type="checkbox"/> Well head tampering                               |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve                  | <input type="checkbox"/> Failed Clamp,        | <input type="checkbox"/> Missing Pipeline/Flowline                         |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow  | <input type="checkbox"/> Third party tampering with Clamp                  |
| <input type="checkbox"/> Third party tampering with valve setting              | <input type="checkbox"/> Bulging Outward      | <input type="checkbox"/> Third party tampering with flange,                |
| <input type="checkbox"/> Flare System/Bund wall failure                        | <input type="checkbox"/> Cold vent            | <input type="checkbox"/> Surge vessel overflow,                            |
| <input type="checkbox"/> Valve Failure   | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 <sup>rd</sup> party equipment impact |
| <input type="checkbox"/> Others(specify) _____                                 |   |  |

**f. Incident caused by:**

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3<sup>rd</sup> party damage   
 Operational  Others (including Mystery spills) \_\_\_\_\_

\*This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire, g) non leaking Theft point removal  
 Version 2019/01  
 Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2530938 JIV report S/N: 1030191

g. Spill point coordinates

h. Measuring unit

WGS 84

Northing:	Easting:
4.945 255	7.184 837
/	/

## C. RISK ASSESSMENT

10. Type of environment:

- Land     
  Swamp     
  Water     
  Seasonal swamp     
  Shoreline/Waterfront

i. Type of environment to which oil has spread:

- Land     
  Swamp     
  Water     
  River (identify) \_\_\_\_\_

ii. Weather condition

- Rain     
  Sunny     
  Dry     
  Wet     
  Windy     
  Hot     
  Cool

11. Distance to Sensitive habitat within 100m radius

- Government reserved and designated protected area
- Drinking water source
- Built up area
- Farmlands
- Fish Farm/Pond
- Fishing net
- Others (specify).

[ ,m] } NONE WITHIN THE  
 [ ,m] } VICINITY  
 [ ,m]  
 [ ,m]  
 [ ,m]

12. Containment measures put in place;

- Booms     
  Trench     
  Dyke     
  Natural depression     
  Pit     
  None  
 Others: \_\_\_\_\_

13. Any pictures or video coverage?

[] [N]

14. Further response/repair initiated as at the time of JIV?

[] [N]

If yes to item 14, give brief description:

REPAIR BY CLAMPING

15. Was there any disruption to the investigation?

[] []

Version 2019/01

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2530938 JIV report S/N: 1030191

If yes to item 15 give brief description:

NOT APPLICABLE

16. Was JIV delayed? [Y] [N]

If yes to item 16 give brief description: NOT APPLICABLE

**D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL**

**17. Structures / Properties**

S/N	Type of Structures	Description	Size	Number	Comments
NONE WITHIN AREA OF IMPACT					

**18. Crops/Economic Trees**

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
NONE WITHIN AREA OF IMPACT						


**19. Fish/Nets/Ponds**

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
NONE WITHIN AREA OF IMPACT				

**20. Others (Specify) i.e. Animal Traps**

S/N	Others	Description	Quantity/Size	Comments
NONE WITHIN AREA OF IMPACT				

**E. GRAPHIC DESCRIPTION OF LEAK POINT** (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1) A SECTION OF 12" IMO RIVER 2 - OGALE PIPELINE AT UMILOLOD SHOWING 1 1/2" PIPE CONNECTED AT 12 O'CLOCK POSITION BY UNKNOWN PERSON(S).





# JOINT INVESTIGATION REPORT

INCIDENT NO: 2530938 JIV report S/N: 1030191

## G. INCIDENT INFORMATION:

### a. Impacted Area Details

- Total calculated area of impact 0.0012 ha
- Impact within SPDC R.O.W. YES
- Impact outside SPDC R.O.W. YES

### b. Volume of oil recovered before completion of JIV ( $V_{rec}$ ):

Recovered oil $V_{rec}$ :	<u>NIL</u>	Barrels
---------------------------	------------	---------

Controlled recovery/evacuation from source with no impact to environment:

<u>NIL</u>	Barrels
------------	---------

c. Net Estimated Spilled Volume  $V_{ES}$  (bbls)\* = 0.17 BARREL

Estimated Reported Volume\*\*  $V_{ER}$  (bbls) = 0.2 BARREL

#### \*Notes:

- Volume estimation was done using an excel based tool. (see attached for details on the calculation)
  - Reported spilled volume is an estimate
- Write other relevant notes taken into consideration for volume estimation or cause of spill:

NOT APPLICABLE

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of  $m^3$  to barrels is Volume ( $m^3$ )  $\times$  6.29; \*\*Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl — Reported volume = 16 bbl  
Calculated volume = 0.35 bbl — Reported volume = 0.4 bbl  
Calculated volume = 0.01 bbl — Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Version 2019/01

Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community).

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2530988 JIV report S/N: 1030191

## d. General Status of the site

- |  |
|--|
| i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/> |
| ii. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/>  |

## e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:


- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Shell Petroleum Development Company [SPDC]:
- *Separate DPR form has been filled out with same findings*:

*Tick as applicable*

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2530938 JIV report S/N: 1030191

f. Appendix 1: Overview sketch of the site



Version 2019/01

Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment) ; Blue (Host Community)