



Overview: Part of spill impact on 20" Kolocreek - Rumuekpe pipeline at Odau KP 9.4 Picture was taken during Joint Investigation of 13th April 2020.



Close-up: 4" ball valve flange installed at 12 o'clock position on 20" Kolocreek - Rumuekpe pipeline at Odau KP 9.4 . Picture was taken during Joint Investigation of 13th April 2020.