



Overview: Part of spill impact on 4" ImoRiver 1 well 36s Flowline at Isietitioha Owaza. Picture was taken during Joint Investigation on 25th August 2020.



Close-up: 4cm Hacksaw cut at 5 to 6 o'clock position on 4" ImoRiver 1 well 36s Flowline at Isietitioha Owaza. Picture was taken during Joint Investigation on 25th August 2020.