



Overview 1: Part of spill impact on 4" Bonny Well 10s Flowline Riser at Oloma. Picture was taken during Joint Investigation 25th May 2020.



Close-up 2: Pin hole Leak on 4" Bonny Well 10s Flowline Riser at Oloma. Picture was taken during Joint Investigation 25th May 2020.