

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2921911 JIV report S/N: 0000842

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

## A. GENERAL INFORMATION:

1. Fountain Incident Number: 2921911 2. Type of incident\* OIL SPILL  
3. Name of Location 20" KOLO CREEK - RUMUEKPE PIPELINE  
4. Name of nearest community OKPOROWO 5. State: RIVERS 6. LGA AITOADA EAST  
7. Production Facility/Installation PIPELINE  
8. Asset Owner/Hub THE STELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED (SPDC)/PIPELINE

## B. INCIDENT INFORMATION:

9. Details of incident  
a. Date Reported: 13<sup>TH</sup> APRIL, 2021  
b. Start date/time of Investigation: 13<sup>TH</sup> APRIL, 2021 / 1320HRS  
c. Investigation End date: 13<sup>TH</sup> APRIL, 2021 Day(s) on site: ONE DAY  
d. Description of spill point environment  
 Firm soil  Loose soil  Recently excavated area  
 Under water  Swampy  Exposed pipe surface  
 Well Platform (on water)  Drill Rig  Sand bag(s)

Additional observations around the spill point:

NOT APPLICABLE

## e. Description of leak point (tick as applicable);

- |  |   |  |
|--|---|--|
| <input type="checkbox"/> Smooth round-edge hole                                | <input type="checkbox"/> Rough-edge hole      | <input type="checkbox"/> Hack saw cut                                      |
| <input type="checkbox"/> Complete Rupture                                      | <input type="checkbox"/> Inward dent,         | <input type="checkbox"/> Well head tampering                               |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve                  | <input type="checkbox"/> Failed Clamp,        | <input type="checkbox"/> Missing Pipeline/Flowline                         |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow  | <input type="checkbox"/> Third party tampering with Clamp                  |
| <input type="checkbox"/> Third party tampering with valve setting              | <input type="checkbox"/> Bulging Outward      | <input type="checkbox"/> Third party tampering with flange,                |
| <input type="checkbox"/> Flare System/Bund wall failure                        | <input type="checkbox"/> Cold vent            | <input type="checkbox"/> Surge vessel overflow,                            |
| <input type="checkbox"/> Valve Failure   | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 <sup>rd</sup> party equipment impact |
| <input type="checkbox"/> Tear ( _____ )  |   |  |
| <input type="checkbox"/> Others (specify) _____                                |   |  |

## f. Incident caused by:

- Third party interference (Sabotage ; crude theft ; Line theft ; Accidental 3<sup>rd</sup> party damage   
 Operational  Others (including Mystery spills) \_\_\_\_\_

\*This can be: (a) Oil Spill (b) Drilling fluid/Chemical (c) Siltation (d) Water Leak (e) Fire (f) Non-leaking theft point removal  
Version 2020/01  
Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment);  
Blue (Host Community)

# JOINT INVESTIGATION REPORT

000842

INCIDENT NO: 2921911 JIV report S/N:

e. Spill(s) at casual sites (incidents > 100m apart to be aggregated into one Joint Investigation Report)

8. Measurement  
Nothing.

(WASS4)

Fasting:

4.971094

6.642493

## C. RISK ASSESSMENT

### 10. Details of Environment

i. Type of environment where spill occurred (select one):

- Land       Swamp       Water       Seasonal swamp       Shoreline/Waterfront

ii. Type of environment to which oil has spread:

- Land       Swamp       Waterbody (specify) \_\_\_\_\_

iii. Weather condition

- Dry       Wet       Windy       Hot

### 11. Distance to Sensitive habitat within 100m radius

- |   |   |     |                               |
|---|---|-----|-------------------------------|
| <input type="checkbox"/> Government reserved and designated protected area                    | [ | .m] | } NON SEEN<br>WITHIN VICINITY |
| <input type="checkbox"/> Drinking water source  | [ | .m] |                               |
| <input type="checkbox"/> Surface water <input type="checkbox"/> Borehole                      |   |     |                               |
| <input type="checkbox"/> Built up Area  | [ | .m] |                               |
| <input type="checkbox"/> Residential Area <input type="checkbox"/> Commercial Industrial Area |   |     |                               |
| <input type="checkbox"/> Farmlands  | [ | .m] |                               |
| <input type="checkbox"/> Fish Farm Pond   | [ | .m] |                               |
| <input type="checkbox"/> Fishing net  | [ | .m] |                               |
| <input type="checkbox"/> Others (specify) _____   | [ | .m] |                               |

### 12. Containment measures put in place:

- Booms     Trench     Dyke     Pit     Natural depression     None
- Others: \_\_\_\_\_

13. Any pictures or video coverage?      [✓]    [N]

14. Further response repair initiated as at the time of JIV?      [Y]    [✓]

For item 14, give brief description:

NONE

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2921911 JIV report S/N: 0000842

15. Was there any disruption to the investigation? [Y]

If yes to item 15 give brief description:

NOT APPLICABLE

16. Was JIV delayed? [Y]

Reason(s):

- Delayed Community Access Approval  
  Security Challenges  
  Access constraint due to terrain  
 Others (specify) NOT APPLICABLE

**D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL**

17. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
<u>NONE SEEN WITHIN AREA OF IMPACT</u>					

18. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
<u>NONE SEEN WITHIN AREA OF IMPACT</u>						


19. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
<u>NONE SEEN WITHIN AREA OF IMPACT</u>				

20. Others (Specify) e.g. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
<u>NONE SEEN WITHIN ARE</u>				

**E. GRAPHIC DESCRIPTION OF LEAK POINT** (while detailed description of the leak point should be contained in the leak report, overview sketch of the site should be added as appendix 1) A SECTION OF 20" KOLO CREEK-RUMUEKPE PIPELINE AT OKPOROWO SHOWING 3" ILLEGAL BALL VALVE INSTALLED AT 12 O' CLOCK POSITION BY UNKNOWN PERSON(S).





# JOINT INVESTIGATION REPORT

INCIDENT NO: 2921911 JIV report S/N: 0000842

## G. INCIDENT INFORMATION:

### a. Impacted Area Details \*

- Total calculated area of impact (Ha) 0.0001 HA
- Impact within SPDC R.O.W YES
- Impact outside SPDC R.O.W NO

\* Round off to 2 decimal places if area is  $\geq 100 \text{ m}^2$  or to 4 decimal places if area is  $< 100 \text{ m}^2$  (e.g. 14.55, 0.0051, 0.0009)  
\* Express in Hectares (Ha)

### b. Volume of oil recovered before completion of JIV ( $V_{\text{rec}}$ ):

Recovered oil $V_{\text{rec}}$ :	<u>NIL</u>	Barrels
----------------------------------	------------	---------

Controlled recovery/evacuation from source with no impact to environment:

<u>NIL</u>	Barrels
------------	---------

### c. Net Estimated Spilled Volume $V_{\text{Est}}$ (bbls)\* = 0.01 BARREL

Estimated Reported Volume\*\*  $V_{\text{rep}}$  (bbls) = 0.1 BARREL

#### \*Notes:

- Volume estimation was done using an excel based tool (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for volume estimation or cause of spill:

ON 13<sup>th</sup> APRIL, 2021, AT ABOUT 14:20 HRS, DURING JIV CRUDE OIL LEAK WAS OBSERVED FROM AN EARLIER REPORTED NON-LEAKING ILLEGAL CONNECTION (FD 2731473) ON 20" KOLO CREEK - RUMUEKPE PIPELINE AT OKPOROWO. THE BURNT VEGETATION IS AS A RESULT OF PREVIOUS ILLEGAL MINING ACTIVITIES AROUND THAT AREA

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of  $\text{m}^3$  to barrels is  $\text{Volume (m}^3) \times 6.29$ ; \*\*Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl  
Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl  
Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Version 2020/01

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2921911 JIV report S/N: 000842

## d. General Status of the site

i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out <input type="checkbox"/>
ii. Investigation of the incident site showed that there is residual impact on site requiring further works <input checked="" type="checkbox"/>

## e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:

- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- The Shell Petroleum Development Company [SPDC]:
- *Separate DPR form has been filled out with same findings*:
- *Separate NOSDRA form has been filled out with same findings*:
- *Separate SME form has been filled out with same findings*:

*Tick as applicable*

# JOINT INVESTIGATION REPORT

INCIDENT NO: 2921911 JIV report S/N: 0000842

f. Appendix 1: Overview sketch of the site

