



Overview: Part of spill impact on 18" Kolocreek Rumuekpe Pipeline at Rumuekpe. Picture was taken during Joint Investigation of 29<sup>th</sup> August 2021.



Close-up: 3inch ball valve installed at 12 o'clock position on 18" Kolocreek Rumuekpe Pipeline at Rumuekpe. Picture was taken during Joint Investigation of 29<sup>th</sup> August 2021.